

2021 Toyota Roomy X		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-M900A	DISPLACEMENT 996 cc		
YEAR / REG. 2021/01	MILEAGE 48,689 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Hatchback		
CHASSIS NO. M900A-0525602	DIMENSIONS (L X W X H) 370 × 167 × 174 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Left side repair history, left center pillar distortion, left rear fender XX, door mirror, wheel CP scratches.			

ORIGINAL JAPANESE AUCTION SHEET

年式 R3 / 1月	メーカー トヨタ	ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 R																				
車種 ミニバン	グレード ルーミー X	駆動方式 2WD	変速機 4WD																					
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	走行距離 48,689 km	走行 48,689 km																				
カラーNo. R67	カラー ワイン	エアロ	オプション A・B・C																					
価格 9,130円	消費税 1,000円	登録料 1000cc	型式 5BA-M900A	型式 A・B・C																				
セールポイント 純正ナビ、地デジTV、バックモニター、スマートアシスト、パワースライドドア、スマートキー、プッシュスタート、ドライブレコーダー																								
検査記入欄 左面修復歴、左センターピラーヒズミ、左RフェンダーXX、ドアミラー、ホイールCPキズ	<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	G	ガラスキズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
登録No. M900A-0525602	名義中																							
車検 M900A-0525602	月 日 まで(名義できる方)																							
FW トピ石	フレ	外装 小	ホイール A・B・C	エアロ A・B・C																				
内装 3D	シス	ヤブレ	コグ	オーディオ																				