

2021 Toyota Sienta G 2		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-NSP170G	DISPLACEMENT 1,496 cc		
YEAR / REG. 2021/06	MILEAGE 15,693 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. NSP170-7283380	DIMENSIONS (L X W X H) 426 × 170 × 168 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking		Power Sliding Doors (Both Sides) (Both... Navigation System	
INSPECTOR REPORT			
Minor scratches on interior trim, exterior wheels.			

ORIGINAL JAPANESE AUCTION SHEET

R3 / 6月		トヨタ		5		ミニバンワンボックス		5																					
シエンタ		Gセーフティエディション2		2WD		4WD																							
車種	自家用・その他 ()	排気量	1500 CC	型式	5BA-NSP170G	通称		内装	①・B・C																				
車検	- 年 - 月 / 日	燃料	ガソリン	ディーゼル		後日選り品 (保証書・取扱説明書等)																							
走行	15,693 km	ソフト	AT																										
外装色	ブラック (209)	カラーNo.	209	AG・AG・WAG ()	装備品のみ O印 を記入																								
内装色	()	乗車定員	7人	①	②	AW	サンルーフ	革シート																					
左・前	左・前	ディーラー	走行	10,360円	エアバッグ	ABS	③	④	キーレス																				
セールスポイント																													
純正ナビ・TV、トヨタセーフティセンス、両側パワースライドドア、バックカメラ、プッシュスタート					修復歴 有 ⑤																								
検査記入欄					<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ/ヘコ</td><td>P</td><td>色あせ/サケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換部</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	へこみ/サレ	B	キズ/ヘコ	P	色あせ/サケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換部	XX	交換済
A	キズ	U	へこみ/サレ	B	キズ/ヘコ	P	色あせ/サケ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換部	XX	交換済																				
室内内張傷小、外ホイール					登録No. 月 日 までに名義できる方																								
					車体番号 NSP170-7283380																								
FW ⑥					シリアル No.																								
内装	ボディ	シロ	ヤブレ	コガ	コガ穴	オーディオ穴	スレ	車輪	最大積載量																				