


2021 Volkswagen VW Polo 5HB TSI Comfortline		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3BA-AWDKL	DISPLACEMENT 999 cc		
YEAR / REG. 2021/12	MILEAGE 10,511 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Hatchback		
CHASSIS NO. WVWZZZAWZMU102437	DIMENSIONS (L X W X H) 406 × 175 × 145 cm		
SALES POINTS			
Alloy Wheels Back Camera Navigation System		Pre-Collision Braking 360° Camera	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R3 / 12月	メーカー フォルクスワーゲン	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4
車名 ポロ	グレード TSIコンフォートライン	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 1000 CC	型式 3BA-AWDKL	選装 型式	内装 A・B・C
車検 8年12月 / 抹消	燃料 ガソリン	ディーゼルのハイブリッド ()	後日選用品 (保証書・取扱説明書等)	
走行 10,511 km	シフト フロア 7 AT			
外装色 ホワイト	カラーNo. ()	エアコン AG・AG・WAG・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5人	サンルーフ	革シート	
左・右 左・右	輸入区分 データー	走行 12,070 km	販売所 エフエフ	TV
セールスポイント ワンオーナー/バックカメラ/横滑り防止装置 (ESC) / 運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/メモリーナビ他/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/ターボ/ミュージックプレイヤー-接続可				
検査記入欄 ドアミラー-A 右Fビラー-W				
				
修復歴 有・無				
A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 擦傷跡 S ヤビ C 腐食 X 交換済 YX 交換済				
登録No. 月 日 までに名義である方				
車体番号 WVWZZZAWZMU102437				
シリアル No.				
FW トビ石	ワレ	外装 小	ホイール	エアロ
内装	シネ	ヤブレ	コガ	コガ穴
長さ	幅	高さ	最大積載量	
406 cm	175 cm	145 cm	Kg	