

2022 BMW BMW X1 xDrive 18d xLine		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3DA-AD20	1,995 cc		
YEAR / REG.	MILEAGE		
2022/02	16,816 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBA32AD0005U14001	446 × 182 × 161 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Roof Rails		Power Tailgate	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Parking Assist (Auto Steering)	
Back Camera		Navigation System	
INSPECTOR REPORT			
Steering wheel wear, pet hair in interior.			

初年度登録	メーカー	BMW	ドア枚数	5	ボディタイプ	SUV/クロカン	評価点																				
R4 /	年式	2月	X 1	グレード	xDrive 18 d xライン		駆動方式 2WD 100																				
車種	自家用 ・ その他 ()		排気量	3000	型式	3DA020	内装																				
車検	-	年	月	日	類別	ガソリン ハイブリッド ()	登録番号																				
走行	1	万	千	百	十	円	AT																				
外装色	パール		カラーNo.	AG・GG・WAG・()		新車品のみ O印 を記入																					
内装色	()		内装色	5人		シート																					
左・(車)	右・(車)	輸入	区分	国産	車種	AT	キーレス																				
セーリングポイント				19,180円 / 月																							
パノラマサンルーフ、パワーバックドア、アダプティブクルーズ、ルーフレール																											
検査記入欄																											
ハンドルスレ、ルーム内動物毛																											
検査履歴 有 () <table border="1"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>ヘンロ</td> <td>B</td> <td>キズ・ヘンロ</td> <td>P</td> <td>検査者・セキ</td> <td>G</td> <td>ガラスキズ</td> </tr> <tr> <td>W</td> <td>傷跡</td> <td>S</td> <td>ヤミ</td> <td>C</td> <td>検査</td> <td>X</td> <td>交換</td> <td>XX</td> <td>交換済</td> </tr> </table> 登録地 月 日 家でなくても可 車体番号 WBA32AD0005U14001								A	キズ	U	ヘンロ	B	キズ・ヘンロ	P	検査者・セキ	G	ガラスキズ	W	傷跡	S	ヤミ	C	検査	X	交換	XX	交換済
A	キズ	U	ヘンロ	B	キズ・ヘンロ	P	検査者・セキ	G	ガラスキズ																		
W	傷跡	S	ヤミ	C	検査	X	交換	XX	交換済																		
FW	()	備A	ワレ	内装	小	キル	エアロ																				
内装	()	シロ	ヤレ	コガ	コガ	オー	ワレ																				