

2022 BMW_Mini BMW Mini 3HB Cooper D Classic Trim		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE XY15MW	DISPLACEMENT 1,496 cc		
YEAR / REG. 2022/06	MILEAGE 20,000 km		
DOORS 3	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Hatchback		
CHASSIS NO. WMW22DJ0702S23324	DIMENSIONS (L X W X H) 387 × 173 × 143 cm		
SALES POINTS			
Alloy Wheels Back Camera		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R4	メーカー MINI	ドア数 3	ボディ形状 コンパクト/ハッチバック	評価点 5		
6月	車名 MINI	グレード クーパーD クラシック・トリム	駆動区分 2WD	AIS検査済み		
車種 自家用・その他()	排気量 1500 cc	型式 XY15MW	通称 型式	内装 A・⑨・C		
車検 - - 年 / 月 / 日	燃料 ガソリン	変速機 ハイブリッド	後日選り品 (保証書・取扱説明書 等)			
走行 20,000 km	シフト フロア 7 AT	記録簿・取説・スペアキー				
外装色 ムーンウォークグレー	カラーNo. ⑨B・AAG・WAG・()	整備品のみ O印 を記入				
内装色 ()	乗車定員 4人	⑨B	⑨C	⑨A		
左・右 左・右	輸入区分 デ	並行	16,240円・預託金	⑨B		
セールスポイント バックカメラ/ESC/横滑り防止装置(ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/HDDナビ/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/ターボ/ミュージックサーバー/ミュージックプレーヤー接続可						
検査記入欄		修復歴 有・⑨				
		A キズ U ヘコみ/サレ B キズ・ヘコみ P 色あせ/ボケ Q ガラスキズ				
		W 補修跡 S サビ C 腐食 X 交換品 XX 交換済				
		登録No. 月 日 までに名変できる方				
		名変中				
		車検番号 WMW22DJ 0702S 23324				
FW トビ石 備A フレ 外装 小 ホイール エアロ	シリアル No.					
内装 ヨゴレ シミ ヤブレ コガ コガ穴 オーディ穴	車種			重量 全重 自重 最大積載量 kg		