


2022 BMW_Mini BMW Mini 5HB Cooper 5 Door Base Grade		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3BA-XU15MW	DISPLACEMENT 1,498 cc		
YEAR / REG. 2022/03	MILEAGE 18,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Hatchback		
CHASSIS NO. WMW32DK0002R70587	DIMENSIONS (L X W X H) 403 × 173 × 145 cm		
SALES POINTS			
Alloy Wheels Navigation System		Pre-Collision Braking	
INSPECTOR REPORT			
Mirror A, door trim A (small), pillar trim A (small), console A (small), no floor mats.			

ORIGINAL JAPANESE AUCTION SHEET

R4 / 3月		MINI MINI		5	コンパクトハッチバック		5																				
車種		白銀用・その他 ()	排気量	1500 cc	型式	3BA-XU15MW	内装																				
車検		9年10月 / 抹消	燃料	ガソリン	ディーゼル	後日選り品 (色選り・取付等)																					
走行		18,205 km	フロア 7 AT																								
外装色		カラーNo. ルーフトップ・グレー・メタリック (B47)	エアコン	④	装備品のみ O印 を記入																						
()		内装色	乗車定員	5人	PS	PW	④ サンルーフ 革シート																				
左・前		デ	走行	17,600円	エ	④	TV																				
セールスポイント																											
クラシックトリム、ナビ、Bカメラ、LEDヘッド、黒ルーフ、ETC				修復歴 有・④																							
検査記入欄				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘビイサレ</td><td>B</td><td>キズ・ヘビイ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換歴</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘビイサレ	B	キズ・ヘビイ	P	色あせ・ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換歴	XX	交換済
A	キズ	U	ヘビイサレ	B	キズ・ヘビイ	P	色あせ・ボケ	G	ガラスキズ																		
W	補修跡	S	サビ	C	腐食	X	交換歴	XX	交換済																		
ミラーA、ドア内張りA<小>、ピラー内張りA<小>、コンソールA<小>、フロアマット無し				登録No. 月 日 までに変更できる方																							
				車体番号 WMW32DK0002R70587																							
FW				シリアル No.																							
内装				Kg																							