


2022 SUBARU Chiffon G Smart Assist		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6BA-LA660F	DISPLACEMENT 658 cc		
YEAR / REG. 2022/05	MILEAGE 14,706 km		
DOORS 5	SEATS 4		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Station Wagon		
CHASSIS NO. LA660F-0004092	DIMENSIONS (L X W X H) 340 × 148 × 178 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking		Power Sliding Doors (Both Sides) (Drive... Back Camera	
INSPECTOR REPORT			
Headliner dirt and stains, left rear wheel arch outer distortion.			

ORIGINAL JAPANESE AUCTION SHEET

R4 / 5月		メーカー スバル		ドア枚数 5	ボディ形状 ステーションワゴン		登録点 3																				
		車名 シフォン		グレード G スマートアシスト	駆動区分 2WD 4WD																						
車種 自家用・その他 ()	排気量 660	型式 CC	6BA-LA660F		通称 型式	内装 A・B・C																					
車検 9年5月 / 抹消	燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書等)																								
走行 14,706マイル	シフト インパネ	AT																									
外装色 シルバー	カラーNo. (S28)	エアコン	装備品のみ O印 を記入																								
()	内装色	乗車定員 4人	サンルーフ 革シート																								
左・前	ディーラー	走行	リサイクル料	7,150円	エブリック	ナビ	TV																				
セールスポイント																											
検査記入欄			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘビイサレ</td><td>B</td><td>キズ・ヘビイ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換品</td><td>XX</td><td>交換時</td> </tr> </table>					A	キズ	U	ヘビイサレ	B	キズ・ヘビイ	P	色あせ・ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換時
A	キズ	U	ヘビイサレ	B	キズ・ヘビイ	P	色あせ・ボケ	G	ガラスキズ																		
W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換時																		
天張り汚れ・染み 左Rタイヤハウスアウター歪み			登録No. _____ 月 _____ 日 _____ までに変更できる方 車体番号 LA660F-0004092																								
FW	トビ	備A	フレ	外装	小	ホイール	エアロ																				
内装	シロ	ヤブレ	コガ	コガ穴	オーディオ	スレ	車種	長さ	最大積載量																		