

2022 CITROEN CITROEN Berlingo Shine		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-K9CYH01	DISPLACEMENT 1,498 cc		
YEAR / REG. 2022/03	MILEAGE 61,489 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Minivan		
CHASSIS NO. VR7ECYHZRMJ926775	DIMENSIONS (L X W X H) 441 × 185 × 185 cm		
SALES POINTS			
Alloy Wheels		Glass Roof	
Roof Rails		Pre-Collision Braking	
Adaptive Cruise Control		Side Camera	
Back Camera			
INSPECTOR REPORT			
No navigation system. Steering wheel wear, seat covers, minor scratches on trim and dashboard. Pet hair present. Minor underbody rust and exterior fading.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 R4 / 3月	メーカー シトロエン	ドア数 5	ボディ形状 ミニバンワンボックス	評価点 4
車名 ベルランゴ	グレード シャイン	駆動方式 4WD	登録区分 4WD	
車種 自家用・その他 ()	排気量 1490 cc	型式 3DA-K9CYH01	登録式 A・C・C	
年 9	月 5	日 5	扶養 扶養	燃料 ガソリン
走行 61,489 km	マイレージ AT	後日選用品 ()	取扱い明書 ()	
外装色 その他	カラーNo. 0	エアコン AG・WAG・WAG ()	新車品のみ・O印を記入	
内装色 その他	乗車定員 5人	PS PS	サンルーフ サンルーフ	車シート 車シート
左・右 左・右	走行 走行	17,930円	エアバッグ ABS	ナビ TV
セールスポイント				
パノラマルー ルーフ BSM パドルシフト				
検査記入欄				
A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損				
名義中				
月 日 まで				
VR7ECYHZRMJ926775				
0 kg				