


2022 Daihatsu Taft 660 G		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6BA-LA900S	DISPLACEMENT 658 cc		
YEAR / REG. 2022/02	MILEAGE 53,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE SUV		
CHASSIS NO. LA900S-0092087	DIMENSIONS (L X W X H) 340 × 148 × 163 cm		
SALES POINTS			
Alloy Wheels Glass Roof Pre-Collision Braking		Sunroof Roof Rails Back Camera	
INSPECTOR REPORT			
Left rear door scratch/damage			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R4 / 2月	メーカー ダイハツ	ドア数 5	ボディ形状 SUV/クワカン	評価値 4.5
車名 タフト	グレード 660 G スマートアシスト/パノラマルーフ/ディスブ	駆動区分 2WD 4WD		
車歴 自家用・その他 ()	排気量 660 cc	型式 6BA-LA900S	通称 正式	年式 A・B・C
車検 9年2月 / 抹消	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)	
走行 53,000 km	インパネ	CVT		
外装色 コンパーノレッド	カラーNo. ()	QD・AAG・WAG・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 4人	(B)	(F)	(A)
オプション 左・(B) 輸入 ディーラー・ 走行	リサイクル料 8,640円	燃費 無	エレクトリック	ナビ TV
セールスポイント キーレスエントリー/ABS/運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/衝突被害軽減ブレーキ/アイドリングストップ/スマートキー/盗難防止システム/LEDヘッドライト/横滑り防止装置 (ESC)/シートヒーター/DVD再生/CD/バックカメラ/障害物センサー				
検査記入欄		修復歴 有・(B)		
左リアドア傷		A キズ U ヘッドランプ B キズ・ヘッド P 熱あせりケ Q ガラスキズ W 破損 S サイズ C 腐食 X 交換 Y 交換 登録No. 月 日 まで(名義できる方) 車体番号 LA900S-0092087		
FR トボ石 傷A フレ 外装 小 ホイル エアロ A・U A・曲 A・フレ	シリアル No.			
内装 ヨゴレ シス ヤブレ コダ コダ穴 オーディオ スレ	長さ cm	幅 cm	高さ cm	最大重量 kg