

2022 Daihatsu Taft G		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LA900S	DISPLACEMENT 658 cc		
YEAR / REG. 2022/12	MILEAGE 41,445 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Brown	BODY TYPE Kei		
CHASSIS NO. LA900S-0118481	DIMENSIONS (L X W X H) 340 × 148 × 163 cm		
SALES POINTS			
Alloy Wheels Glass Roof Pre-Collision Braking Navigation System		Sunroof Roof Rails Back Camera	
INSPECTOR REPORT			
Rear wiper missing. Large stain on rear seat. Medium scuff on headliner. Medium stain on carpet. Small scratch on console.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 R4 / 12月	メーカー ダイハツ	ドア数 5	ボディ形状 軽四	評価点 4
車名 タフト	グレード G	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 660 cc	型式 LA900S	型式 A・B・C	内装 A・B・C
年式 9年12月	扶養 なし	燃料 ガソリン	ディーゼル	後付部品 (保証書・取扱説明書等)
走行 41,445 km	インパネ	AT		
外装色 サンベージュメタリック	カラーNo. ()	エアコン (Q・A・G・W・A・D・C)	新着品のみ・O印を記入	
内装色 ()	乗車定員 人	人	PS	PS
左・右 左・右	ディーラー 直行	リサイクル料 8,200円	販売税 エレクト	TV
セールスポイント				
バックカメラ/ETC/横滑り防止装置 (ESC) /運転席エアバック/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/メモリーナビ他衝突被害軽減ブレーキ/アイドリングストップ/シートヒーター				
修復歴 有・無				
検査記入欄				
リアワイパー欠陥 リアシートしみく大 障害A < 中 > 天板りすれく中 > カーペットしみく中 > コンソールA < 小 >				
A 欠陥 B 欠陥 C 欠陥 D 欠陥 E 欠陥 F 欠陥 G 欠陥 H 欠陥 I 欠陥 J 欠陥 K 欠陥 L 欠陥 M 欠陥 N 欠陥 O 欠陥 P 欠陥 Q 欠陥 R 欠陥 S 欠陥 T 欠陥 U 欠陥 V 欠陥 W 欠陥 X 欠陥 Y 欠陥 Z 欠陥				
名義中 月 日 まで名義で販売				
車体番号 LA900S-0118481				
車種 軽四				
長さ cm				
幅 cm				
高さ cm				
最大積載量 kg				