

2022 Daihatsu Thor 1.0G		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-M900S	DISPLACEMENT 996 cc		
YEAR / REG. 2022/12	MILEAGE 9,066 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Hatchback		
CHASSIS NO. M900S-1002629	DIMENSIONS (L X W X H) 370 × 167 × 174 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Both... Back Camera		Pre-Collision Braking	
INSPECTOR REPORT			
Third-party inspection completed. Main equipment confirmed OK. Light stains inside the cabin. Wheel CP crack. Minor rust underneath. Small scratches.			

出 品 票		型式認定番号	製造国(地名)	シリアル番号	評 価 点
前年度登録 R04 年 12月	車 名 トール	シア数 5	グ レ ー ド 1.0 Gスマートキー 両側電動スライドドア	車種 4WD 2700cc 4速AT	5
型式 5BA-M900S		排気量 1000 cc	燃料 灯油	内 燃	日 本
車 種 年 月	年 月 2004 06	車 型 車 種 自家用	シフト DAT	内 燃 AC	純正装備品 ○をつける 純正ナビ ○ 純正ナビ 車シート ○ 純正ナビ 車シート ○ ナビ機器(社外品含む) ○をつける フルセグ ワンセグ デジタル ナビ機器(社外品含む) ○をつける HDD内蔵 ○ DVD内蔵 ○ 後日取付け品 ○をつける 後日取付け品 ○ 後日取付け品 ○
走行距離 万 千 0 6 6 km	メール (交換) (改ざん) (不明)	カラー 色 目 ターコイズブルー 色 目 ()	カラー 色 目 ()	内 燃 AC	走行距離 万 千 0 6 6 km
外装色 ターコイズブルー	車 種 M900S	車 種 1002629	リサイクル 排気量 9,610	内 燃 AC	走行距離 万 千 0 6 6 km
登録No. 5	車 種 M900S	車 種 1002629	リサイクル 排気量 9,610	内 燃 AC	走行距離 万 千 0 6 6 km
定員 5	車 種 M900S	車 種 1002629	リサイクル 排気量 9,610	内 燃 AC	走行距離 万 千 0 6 6 km
輸入元 セールスポイント スマートキー 両側電動スライドドア	車 種 M900S	車 種 1002629	リサイクル 排気量 9,610	内 燃 AC	走行距離 万 千 0 6 6 km

注意事項・不具合箇所

☆第三者機関検査済み☆

検査員記入欄：取付け「有」の場合は取付け後、交換品を記入

☆主要装備確認OK☆

ルーム内汚し

ホイールCPワレ

下廻り小サビ

小キズ