

|                                                    |                        |                                           |          |
|----------------------------------------------------|------------------------|-------------------------------------------|----------|
| 2022 Daihatsu Thor Custom 1.0 Custom G             |                        | OVERALL                                   |          |
|                                                    |                        | 4                                         |          |
|                                                    |                        | EXTERIOR                                  | INTERIOR |
|                                                    |                        | -                                         | -        |
| MODEL CODE                                         | DISPLACEMENT           |                                           |          |
| 5BA-M900S                                          | 996 cc                 |                                           |          |
| YEAR / REG.                                        | MILEAGE                |                                           |          |
| 2022/03                                            | 49,000 km              |                                           |          |
| DOORS                                              | SEATS                  |                                           |          |
| 5                                                  | 5                      |                                           |          |
| DRIVETRAIN                                         | TRANSMISSION           |                                           |          |
| 2WD (FF)                                           | AT                     |                                           |          |
| FUEL                                               | STEERING               |                                           |          |
| Petrol                                             | Right                  |                                           |          |
| EXTERIOR COLOR                                     | BODY TYPE              |                                           |          |
| Black                                              | Hatchback              |                                           |          |
| CHASSIS NO.                                        | DIMENSIONS (L X W X H) |                                           |          |
| M900S-0090527                                      | 371 × 167 × 174 cm     |                                           |          |
| SALES POINTS                                       |                        |                                           |          |
| Alloy Wheels                                       |                        | Power Sliding Doors (Both Sides) (Both... |          |
| Pre-Collision Braking                              |                        | Navigation System                         |          |
| INSPECTOR REPORT                                   |                        |                                           |          |
| Core support bent, lower support damaged, each AUW |                        |                                           |          |

|                          |  |                     |  |                                          |  |                             |  |                 |  |
|--------------------------|--|---------------------|--|------------------------------------------|--|-----------------------------|--|-----------------|--|
| 初年度登録                    |  | メーカー<br><b>ダイハツ</b> |  | ドット数<br>5                                |  | ボディ形状<br>コンパクトハッチバック        |  | 評価点<br><b>4</b> |  |
| <b>R4 /</b><br><b>3月</b> |  | 車名<br><b>トール</b>    |  | グレード<br><b>1.0カスタムGキーフリー<br/>全周囲モニター</b> |  | 駆動区分<br>2WD<br>4WD          |  |                 |  |
| 車種<br>良薬用・その他( )         |  | 排気量<br>1000 CC      |  | 型式<br>5BA-M900S                          |  | 運転形式                        |  | 内装<br>A・B・C     |  |
| 乗員<br>9人                 |  | 燃料<br>ガソリン          |  | ディーゼル                                    |  | 検日番号貼 (保証書・取扱説明書等)          |  |                 |  |
| 走行<br>49,000km           |  | シフト<br>ハイブリッド       |  | CVT                                      |  |                             |  |                 |  |
| 外装色<br>ブラックマイカメリック       |  | カラーNo.<br>( )       |  | エンジン<br>AA・AAC・WAG・( )                   |  | 装備品のみ O印 を記入                |  |                 |  |
| ( )                      |  | 内装色                 |  | 標準定員<br>5人                               |  | オプション<br>F9 F7 AM サンルーフ革シート |  |                 |  |
| パネ<br>左・右                |  | 入庫<br>ディーラー・並行      |  | リサイクル料<br>9,720円 + 預託金                   |  | EPA A B C D E               |  |                 |  |

**セールスポイント**

キーレスエントリー/A B S /運動席エアバック/助手席エアバック/メモリーナビ付/フルセグTV/衝突被害軽減ブレーキETC/アイドリイングストップ/スマートキー/盗難防止システムオートクルーズコントロールLEDヘッドライト横滑り防止装置(E S C) /フルフラットCD全周囲カメラ/バックカメラ/障害物センサー/両側電動スライドドア

**検査記入欄**

コアサポートゆがみ  
コアサポート××

各AUW

**修復歴**  
有。( )

|      |                                            |   |       |   |       |   |        |    |      |
|------|--------------------------------------------|---|-------|---|-------|---|--------|----|------|
| A    | 劣化                                         | U | ヘコミヤレ | B | 劣化ヘコミ | P | 劣化ヤレボテ | G  | ガラス割 |
| W    | 修繕跡                                        | S | サビ    | C | 腐食    | X | 交換済    | XX | 交換済  |
| 登録地  | 月                日                までに変更できる |   |       |   |       |   |        |    |      |
| 車体番号 | M900S-0090527                              |   |       |   |       |   |        |    |      |

|    |     |    |     |    |          |             |                    |
|----|-----|----|-----|----|----------|-------------|--------------------|
| FW | トピ石 | 傷A | フレ  | 外装 | 小<br>A・U | ホイール<br>A・曲 | エアロ<br>シリアル<br>No. |
| 内装 | ヨゴレ | シミ | ヤブレ | コゲ | コガレ      | オーディオ       | スレ                 |