

2022 ES ES300h Version L		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6AA-AXZH11	DISPLACEMENT 2,487 cc		
YEAR / REG. 2022/01	MILEAGE 57,125 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Sedan		
CHASSIS NO. AXZH11-1006044	DIMENSIONS (L X W X H) 498 × 187 × 145 cm		
SALES POINTS			
Alloy Wheels Leather Seats (Semi-aniline Leather) Navigation System		Sunroof Adaptive Cruise Control Lexus ES Premium Sound System (8 Sp...	
INSPECTOR REPORT			
Scratches on trim, door mirrors, and outer left front fender mirror.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R4 / 1月	メーカー レクサス	ドア枚数 4	ボディ形状 セダン	年価点 4
車名 E S	グレード ES300h パー ジョンL	駆動区分 2WD 4WD		
車歴 自家用・その他 ()	排気量 2500 cc	型式 6AA-AXZH11	通称 正式	内装 A・⑤・C
車検 9年1月 / 抹消	燃料 ハイブリッド ()	ディーゼル シフト	後日選り込み (⑥) 等・取説等 (等)	
走行 57,125 km	AT			
外装色 パール	カラーNo. 085	AG・⑥・WAG・ ()	新着品のみ O印 を記入	
内装色 ()	乗車定員 5人	⑤	⑥	⑦
左・ (新) 輸入 ディーラー・ 走行 11,790 km	ボディカラー 11,790 km	エアバック	ABS	⑧
セールスポイント 後期モデル、サンルーフ、黒本革エアシート、メーカナビ、フルセグTV、バックモニター、レクサスセーフティシステム、レーダークルーズコントロール、ブリクラッシュセーフティ、ビルトインETC				
検査記入欄 トリムキズ、ドアミラーキズ、外左Fフェンダーミラー？		修復歴 有・ (⑨)		
		A キズ U ヘッドランプ B キズ・ヘッド P 熱劣化・サケ Q ガラスキズ W 補修品 S サビ C 腐食 X 交換品 YX 交換品 登録No. 月 日 までに名義できる方 車体番号 AXZH11-1006044		
内装 ⑩	シエ ヤブレ	コグ コグ穴	オーディオ オーディオ	シリアル No.
重量 cm	幅 cm	高さ cm	最大積重量 kg	