

2022 Honda N-VAN 660 G		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BD-JJ1	DISPLACEMENT 658 cc		
YEAR / REG. 2022/07	MILEAGE 32,534 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Hatchback		
CHASSIS NO. JJ1-5010476	DIMENSIONS (L X W X H) 340 × 148 × 195 cm		
SALES POINTS			
Pre-Collision Braking Navigation System		Adaptive Cruise Control	
INSPECTOR REPORT			
Cargo area scratches and dents, side mirror scratches, left front inner panel bent, lower support bent.			

初年度登録		メーカー ホンダ		ドア数 5		ボディ形状 コンパクトハッチバック		原価点	
R4 / 7月		車名 N-VAN +スタイル		グレード 660 G ナビ TV ホンダセンシング		駆動区分 4WD		R	
車種 良用途・その他()		排気量 660 CC		型式 5BD-JJ1		運転形式		内装 A・B・C	
車検 - - 年 月 日		燃料 ガソリン		ディーゼル		後日返却品 (緑書・取扱い明書等)			
走行 口内にマークを記入(※交換 ※盗損 ※失窃) [] 内 [] 外 [] 両方 [] その他 []		シフト ハイブリッド							
マイレージ 32,534 km		インパネ CVT							
外装色 白		カラーNo.		エディション AG・WG・WAG・()		交換品のみに O印 を記入			
()		内装色		標準定員 4人					
ハンドル 左・右		出入り ディーター・並行		リサイクル料 7,510円		エコパック		AW サルーフ 革シート	

セールスポイント

キーレスエントリー/A B S /運動席エアバック/助手席エアバック/メモリーナビ他/ワンセグTV/衝突被害軽減ブレーキ/アイドリイングストップ/盗難防止システム/オートクルーズコントロール/横滑り防止装置(E S C) /D V D再生/C/D/両側スライド

検査記入欄

荷室芝刈込み
サイドミラーキズ
左フィンサイドパネル曲がり
ロアサポート曲がり

修復歴
②、無

A	文字	U	へこみヤレ	B	文字へこみ	P	熱変色・ボサ	G	ガラスキズ
W	修繕跡	S	サビ	C	腐食	X	交換済	XX	交換済
登録No.	月 日 まで(に各号である)								
車体番号	JJ1-5010476								

FW	トコナ	備A	フレ	外装	小 ③・④	ホイール A・曲	エアロ A・フレ	シリアル No.	最大積載量
内装	ヨゴレ	シミ	ヤブレ	コゲ	コガレ	オーデイオ	スレ	車庫	最大積載量