

2022 Levorg GT-H STI Front Lip Power Back Door		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 4BA-VN5	DISPLACEMENT 1,795 cc		
YEAR / REG. 2022/03	MILEAGE 40,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Station Wagon		
CHASSIS NO. 035562	DIMENSIONS (L X W X H) 476 × 180 × 150 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Cruise Control		STI Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Exterior scratches and dents, studless tires, seat stains and burn holes, interior scuffs and dirt.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R4 / 3月	メーカー スバル	ドア数 5	ボディ形状 ステーションワゴン	評価点 4
車名 レヴォーグ	グレード GT-H STIフロントリッ リップ パワーバックドア	駆動区分 2WD	2WD	
車種 自家用・その他 ()	排気量 1800 cc	型式 4BA-VN5	通称 形式	内装 A・B・C
年 -	月 -	日 -	燃料 ガソリン	ディーゼル
走行 40,000 km	シフト フロア CVT	後日送り品 ()	取付 ()	等 ()
外装色 マグネタイトグレー・メタリック	カラーNo. ()	QD・AAG・WAG・()	装備品のみ O印 を記入	
内装色 ()	車庫 ()	人 ()	サンルーフ	シート
左・右 ()	ディーラー ()	走行 ()	10,780円	取付 ()
セールスポイント アイサイト！STIフロントリップ！LEDヘッドライト！ パワーバックドア！社外メモリーナビ！フルセグ！ Bluetooth！バックカメラ！シートヒーター！ETC！ス マートキー！				
検査記入欄 外装キズ、凹 スタッドレスタイヤ シートシミ、コゲレ 室内スレ、ヨゴレ				
修理歴 有 ()				
A キズ U ヘッドランプ B キズ・ヘッ P 色あせ・サケ Q ガラスキズ W 修理済 S サビ C 腐食 X 交換済 XX 交換済 車体番号 035562				
内装 ()				