

2022 MAZDA Carol 5D Hybrid GS 4WD Dual Camera Brake Start-off Suppression		OVERALL	
		6	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
5AA-HB97S	657 cc		
YEAR / REG.	MILEAGE		
2022/03	11,158 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
HB97S-100164	340 × 148 × 153 cm		
SALES POINTS			
Pre-Collision Braking			
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R4/3月	メーカー マツダ	ドア枚数 5	ボディ形状 軽四	評価点 6					
車名 キャロル	グレード ハイブリッドGS 4WD デュアルカメラブレーキ 誤発進抑制	駆動区分 2WD	1000						
車種 自家用・その他 ()	排気量 660 CC	型式 5AA-HB97S	車体形式 A・B・C						
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	後日選り品 ()						
走行 11,158 km	インパネ	AT	新車保証書・車載取説・手帳・スペアキー						
外装色 パール	カラーNo. (ZVR)	エアコン	装備品のみ O印 を記入						
内装色 ()	乗車定員 4 人	AW	サンルーフ	革シート					
左・右 左・右	ディーラー	走行	7,210円・預託金	エレクトロニック					
セールスポイント									
ハイブリッド・4WD・セーフティサポート・デュアルカメラブレーキサポート・誤発進抑制機能・レーンディパーチャアラート・パーキングセンサー・クリアランスソナー・アイドリングストップ・キーレスキー・社外CDオーディオ・ビルトインETC・左右シートヒーター・電動格納ミラー・ヒートッドミラー・Pガラス・Rワイパー・フロアマット・内外装仕上げ済み									
検査記入欄									
修復歴									
有 ()									
A	キズ	U	へき・オサレ	B	キズ・へき	C	色あせ・ボケ	G	ガラスキズ
W	被修理	S	サビ	C	腐食	X	交換	XX	交換
登録No.					名義中				
月 日					までに名義できる方				
車体番号					HB97S-100164				
FW	トビ石	機A	フレ	外装	小	ホイール	エアロ	シリアル	No.
内装	ヨゴレ	シミ	ヤブレ	コゲ	コゲ穴	オーディオ穴	スレ	長さ	cm
					長さ	cm	長さ	cm	最大積重量
					kg				