

| 2022 Mazda CX-5 2.2 XD PROACTIVE                                                                                 |                                              | OVERALL                                              |          |
|------------------------------------------------------------------------------------------------------------------|----------------------------------------------|------------------------------------------------------|----------|
|                                                                                                                  |                                              | EXTERIOR                                             | INTERIOR |
|                                                                                                                  |                                              | -                                                    | -        |
| MODEL CODE<br>3DA-KF2P                                                                                           | DISPLACEMENT<br>2,188 cc                     |                                                      |          |
| YEAR / REG.<br>2022/10                                                                                           | MILEAGE<br>66,742 km                         |                                                      |          |
| DOORS<br>5                                                                                                       | SEATS<br>5                                   |                                                      |          |
| TRANSMISSION<br>AT                                                                                               | FUEL<br>Diesel                               |                                                      |          |
| STEERING<br>Right                                                                                                | EXTERIOR COLOR<br>Other                      |                                                      |          |
| BODY TYPE<br>Other                                                                                               |                                              |                                                      |          |
| CHASSIS NO.<br>KF2P-518542                                                                                       | DIMENSIONS (L X W X H)<br>457 × 184 × 169 cm |                                                      |          |
| SALES POINTS                                                                                                     |                                              |                                                      |          |
| Alloy Wheels<br>Adaptive Cruise Control<br>Side Camera                                                           |                                              | Pre-Collision Braking<br>Front Camera<br>Back Camera |          |
| INSPECTOR REPORT                                                                                                 |                                              |                                                      |          |
| Exterior light line scratches, steering wheel scuff, interior dirt, interior trim scratches, seat wear and dirt. |                                              |                                                      |          |

ORIGINAL JAPANESE AUCTION SHEET

|                                |             |          |        |          |        |                  |        |        |        |        |
|--------------------------------|-------------|----------|--------|----------|--------|------------------|--------|--------|--------|--------|
| 出品票                            |             | 18797    |        | 0551     |        | シリアリ車庫           |        | 評価点    |        |        |
| R 04                           |             | CX-5     |        | 5        |        | 2.2 XD PROACTIVE |        | 4.5    |        |        |
| 10月                            |             | 3DA-KF2P |        | 2,200 cc |        | 燃料: ガソリン         |        | A C    |        |        |
| 車種                             | R 09        | 10月      | 車次     | 10       | 車種     | 自家用              | シフト    | AT     | 治具     | AC     |
| 走行距離                           | 6           | 6        | 7      | 4        | 2      | km               | マイル    | 0      | 0      | 0      |
| 外装色                            | パール         | 色目       | 色目     | 色目       | 色目     | カラーNo.           | 内装色    | 色目     | 色目     | 色目     |
| 車台No.                          | KF2P-518542 |          |        |          | ボディNo. | 11,710           | 内装No.  | 11,710 | ボディNo. | 11,710 |
| 登録No.                          | 千葉          | 登録       | 11,710 | 登録       | 11,710 | 登録               | 11,710 | 登録     | 11,710 | 登録     |
| 定乗                             | 5 (人)       | 乗員       | kg     | 457      | cm     | 184              | cm     | 169    | cm     | cm     |
| 輸入車のみ                          | モデル         | 型式       | 輸入     | ディーラー    | 型行     | ハンドル             | 左      | 右      | 左      | 右      |
| セールスポイント                       |             |          |        |          |        |                  |        |        |        |        |
| 注意事項・不具合箇所                     |             |          |        |          |        |                  |        |        |        |        |
| 検査員記入欄: 検査員「有」の場合は検査箇所・交換箇所を記入 |             |          |        |          |        |                  |        |        |        |        |
| 外装うすい線キズ                       |             |          |        |          |        |                  |        |        |        |        |
| ハンドルすれ                         |             |          |        |          |        |                  |        |        |        |        |
| 室内汚れ                           |             |          |        |          |        |                  |        |        |        |        |
| 室内内装傷                          |             |          |        |          |        |                  |        |        |        |        |
| シートへたり、汚れ                      |             |          |        |          |        |                  |        |        |        |        |
| トリアミラー                         |             |          |        |          |        |                  |        |        |        |        |
| キズ                             |             |          |        |          |        |                  |        |        |        |        |
| シヤッキ                           |             |          |        |          |        |                  |        |        |        |        |
| フレ                             |             |          |        |          |        |                  |        |        |        |        |