

2022 MercedesBenz Benz GLC Class GLC220d 4MATIC Sportline Edition		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-253915C	DISPLACEMENT 1,949 cc		
YEAR / REG. 2022/08	MILEAGE 16,817 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE SUV		
CHASSIS NO. W1N2539152G113981	DIMENSIONS (L X W X H) 467 × 189 × 165 cm		
SALES POINTS			
Alloy Wheels Leather Seats Power Seats (Front) Adaptive Cruise Control Side Camera Navigation System		Roof Rails Power Tailgate Pre-Collision Braking Front Camera Back Camera	
INSPECTOR REPORT			
Front windshield has a stone chip. Interior has dirt/stains. Wheels and aero parts have A-grade scratches/cracks.			

初年度登録	メーカー メルセデス・ベンツ		ドア数 5		ボディ形状 SUV/クロカン		評価点 4.5
R4 /	8月		グレード GLC 220 d 4マチック スポーツラインエディション		駆動方式 2WD		4.5
車種 自家用・その他 ()	排気量 1940	CC	型式 3DA-253915C	運転席側	内装 A・C・D		
車検 9年8月	検出 ガソリン	燃料 ハイブリッド ()	モーター AT	後部座席数 () 座・取説に明記等 ()			
走行 16,817km	シフト						
外装色 グレー (831)	カラーNo. AG・GAG・WAG・()	新車品のみ O印 を記入					
()	内装色 その他	乗車定員 5人	PS	7	AM	サンルーフ	リアドア
左・右・後 700cc・走行	700cc・走行	17,580円	エンジン	ABS	ナビ	TV	キーレス
セールスポイント							
検査記入欄			修復歴 有 ()				
内装 ハンドルスレ シートレス トリムA			A キズ U ヘッドレスト B キズヘッド C 助手席・シート X 交換済 XX 交換済 W 補修済 S キズ C 腐食				
外装 補修A			登録地 月 日 家で名義変更済み				
内装 ボディ シロ サゲル			車体番号 W1N2539152G113981				
外装 ボディ シロ サゲル			シリアルNo.				