

2022 MercedesBenz Benz GLS Class GLS580 4MATIC Sport		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 4AA-167986	DISPLACEMENT 3,982 cc		
YEAR / REG. 2022/01	MILEAGE 14,050 km		
DOORS 5	SEATS 7		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Left		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. W1N1679861A481425	DIMENSIONS (L X W X H) 522 × 203 × 183 cm		
SALES POINTS			
Alloy Wheels Roof Rails Power Tailgate Pre-Collision Braking Parking Assist (Auto Steering) Side Camera Navigation System		Sunroof Leather Seats Power Seats (Front) Adaptive Cruise Control Front Camera Back Camera Burmester Surround Sound System (13 ...	
INSPECTOR REPORT			
Minor scratches, light scratches, small dents, stone chips, repair marks on the right side, and interior wrinkles/scuffs.			

ORIGINAL JAPANESE AUCTION SHEET

R4 / 1月		メルセデス・ベンツ		5		SUV/クロカン		4.5	
GLS		GLS580 4マ		2WD		4WD			
チェックスポーツ									
車種 自家用・その他 ()		排気量 4000 cc		型式 4AA-167986		登録区分		A・B・C	
年 9年 1月		燃料 ガソリン		ディーゼル		後付選用品 ()			
走行 14,050 km		シフト フロア 9 AT		エアコン		新車品のみ O印 を記入			
外装色 オブシディアンブラック		カラーNo.		AG・AGC・WAG・()		新車品のみ O印 を記入			
内装色		乗車定員 7人		エアコン		新車品のみ O印 を記入			
22,300円		ノリカル料		22,300円		新車品のみ O印 を記入			
セールスポイント		- Burmesterサウンド - パノラミックスライディングルーフ - ブラックレザー - メモリー付きパワーシート - ベンチレーション&シートヒーター				修復歴 有 ()			
検査記入欄		・小キズ・ウスキズ・小ヘコミ・トビ石・右側面補修跡・内装シワ/スレ		A キズ B 凹み C ヘコミ D 傷 E 汚れ F 錆 G 変色 H 変形 I 欠損 J 変質 K 変質 L 変質 M 変質 N 変質 O 変質 P 変質 Q 変質 R 変質 S 変質 T 変質 U 変質 V 変質 W 変質 X 変質 Y 変質 Z 変質		名義中			
W1N1679861A481425									
522 cm		203 cm		182 cm		最大積載量		kg	