

2022 MITSUBISHI Delica D5 G Power Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-CV1W	DISPLACEMENT 2,267 cc		
YEAR / REG. 2022/02	MILEAGE 33,595 km		
DOORS 5	SEATS 8		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Minivan		
CHASSIS NO. CV1W-3001778	DIMENSIONS (L X W X H) 480 × 180 × 188 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Power Sliding Doors (Both Sides) (Both...		Power Tailgate	
Pre-Collision Braking		Adaptive Cruise Control	
INSPECTOR REPORT			
Front windshield stone chip. Interior: dirt, stains, tears, burns, burn holes, audio holes, scuffs. Exterior: small scratches, small dents, bends, scratches, cracks. Wheels: scratches, cracks. Aero			

ORIGINAL JAPANESE AUCTION SHEET

R4 / 2月		メーカー 三菱		ドア数 5		ボディ形式 ミニバン/ワンボックス		評価点 4	
車名 デリカD : 5		グレード G パワーパッケージ		駆動方式 2WD		燃費区分 490			
車種 自家用 ・ その他 ()	排気量 2260 CC	型式 3DA-CV1W	通称 3DA	内装 A・B・C					
車検 9年2月 / 抹消	燃料 ガソリン	変速機 デュアル	後付部品 ()						
走行 33,595 km		変速機 AT							
外装色 ブラック	カラーNo. X42	エアコン AG・AG0・WAG・()	後付部品のみ O印 を記入						
内装色 ()	その他	乗車定員 8人	PS	ABS	ナビ	サンルーフ	キーレス		
左・右・前・後・走行	ディーラー・走行	13,750円	エアロ	ABS	ナビ	TV	キーレス		
セールスポイント			アルパインナビ シートヒーター HDMI端子						
検査記入欄			修復歴 有・無						
A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損			A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損						
CV1W-3001778			CV1W-3001778						
0 kg			0 kg						