


2022 LEXUS RC RC300 F Sport		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
ASC10	1,998 cc		
YEAR / REG.	MILEAGE		
2022/06	8,754 km		
DOORS	SEATS		
2	4		
DRIVETRAIN	TRANSMISSION		
2WD (FR)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	Coupe		
CHASSIS NO.	DIMENSIONS (L X W X H)		
ASC10-60026677	470 × 184 × 140 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Leather Seats (Leather)		Adaptive Cruise Control	
Navigation System		Lexus RC Premium Sound System (10 s...	
INSPECTOR REPORT			
Front inner panel wave/wrinkle			

前年度登録		メーカー		ドア枚数		ボディ形状		特価点	
R4 / 6月		レクサス RC		グレード RC300 F S ポーツ		車軸区分 2WD 4WD		R	
車種 自動車・その他()		排気量 3000 CC		型式 ASC10		運転形式		内装 A (B) C	
年表 [] 9 年 [] 6 月 / 扶消		燃料 ガソリン		ディーゼル		償還率(%) (保証書・取扱説明書等)			
走行 口付にヤブ付取人(名・交機) ● (住所) (市・町・区) 左 方 子 右 田 子 子 [] [] [] [] 8 , [] 7 5 4 [] マイル		シフト フロア 8 AT							
外装色 ホワイトノヴァグラスブラック		カラーNo.		エンジン QW・AAD・WAG・()		新価格のみ O印 を記入			
() 在庫車は() (内装色)		積算定員		4 人		☐ P ☐ F ☐ A ☒ サブーフ ☒ 乗込			
シモ		左・右(輸入区分)		ディーラー		運行		リサイクル料	
		15,080円		買取額		E/Fバック		☐ E/Fバック	

セールスポイント

ムーンルーフ
ホワイトレザーシート
三眼フルLEDヘッドライト
純正ナビ
バックカメラ
フルセグ
シートヒーター＆ベンチレーション
ステアリングヒーター
F専用19AW



検査記入欄

FインナーW

A	キズ	U	へこみサビ	B	キズへこみ	P	色あせ・ボケ	G	ガラスキズ
W	傷跡跡	S	サビ	C	腐食	X	交換歴	XX	交換済
査検No.									査定
月									日
事故番号									ASC10-60026677

FW	(シボ)	備A	ワレ	外装	小 ①	ホイル ②	エアロ ③	シリアル ④
内装	(シボ)	シミ	ヤブレ	コゲ	⑤	⑥	⑦	⑧