

2022 Subaru Levorg 2.4 STI Sport R EX		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-VNH	DISPLACEMENT 2,387 cc		
YEAR / REG. 2022/10	MILEAGE 60,535 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Other		
CHASSIS NO. VNH-004942	DIMENSIONS (L X W X H) 475 × 179 × 150 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Pre-Collision Braking Cruise Control		Power Tailgate Leather Seats (Leather) Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Scratches and dents, spoiler scratches, wheel scratches, front glass stone chips, interior scratches/scuffs/dirt, seat wrinkles.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		型式番号	20302	車両識別番号	5002	シリアル番号		評価点	
年式	車名	グレード	駆動	評価点					
R 04	レヴォーグ	2.4 STI Sport R EX	2WD	4.5					
10月	型式	5BA-VNH	排気量	2,400 cc	燃料	ガソリン	軽油	内装	A B C
車検	R 09	年	10月	用途	自家用	シフト	AT	変速	AC
走行距離	6	0	5	3	5	マイル	km	色	白
外装色	メタリック	色	白	カラーNo.		内装色		純正ナビ	SR
車検No.	VNH-004942	名義	個人	月	日	納期		純正ナビ	SR
登録No.	和泉	397	主	358	リサイクル	10,780円	円	純正ナビ	SR
定価	5	人	種別	kg	475	cm	179	cm	150
輸入車	モーター	車	輸入国	ディーラー	認定	ハンドル	左	ナビ	ナビ
セーレスポイント									
後期型	乗用車	純正12.3インチ	7インチ	6インチ	赤革シート	シートヒーター	ナビ		
注意事項・不具合箇所									
検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入									
傷へこみ									
スポイラー類傷									
ホイール傷									
FG破損									
内装傷・汚れ									
シートしわ									
ドアミラー	キズ	ヒビ	汚れ	1点	無	シヤシヤ	無		