


2022 Suzuki ALTO LAPIN L		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
HE33S	658 cc		
YEAR / REG.	MILEAGE		
2022/12	21,500 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Green	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
HE33S-405360	340 × 148 × 153 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Right front side member repaired. Right front fender stay bent.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R4 / 12月	メーカー スズキ	ドア枚数 5	ボディ形状 軽四	評価点 R																				
車名 アルトラパン	グレード L	駆動区分 2WD																						
車種 自家用・その他 ()	排気量 660 cc	型式 HE33S	通称 軽四	内装 A・B・C																				
車検 9年8月	燃料 ガソリン	ディーゼル ハイブリッド ()	後日送り品 ()																					
走行 21,500 km	シフト CVT	スマートキー																						
外装色 グリーン	カラーNo. ()	エアコン AG・QG・WAG ()	新着品のみ O印 を記入																					
内装色 ()	乗車定員 4人	AW サンルーフ 革シート																						
左・右 左・右	輸入 区分	ディーラー 並行	5,670円	5,670円																				
セールスポイント ワンオーナー・LEDヘッドライト・セーフティサ ポート・シートヒーター・フルセグナビ・前後ドライ ブレコーダー・禁煙車・スマートキー×2																								
特記事項 グー鑑定済み		修復歴 0																						
検査記入欄 右フロントサイドメンバー修正。 右フロントフェンダーステー曲がり。		<table><tr><td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ・へこみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td></tr><tr><td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td></tr></table>			A	キズ	U	へこみ/サレ	B	キズ・へこみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	へこみ/サレ	B	キズ・へこみ	P	色あせ/ボケ	G	ガラスキズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
		登録No. 月 日 までに名義できる方																						
		車検 HE33S-405360																						
FW トビ	備A	ワレ	外装 小	内装 A・U	エアロ A・ワレ	シリアル No.																		
内装 30	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	スレ	長さ cm	幅 cm	最大積載量 kg															