

2022 Toyota Corolla Touring Double VVi		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3BA-ZRE212W	DISPLACEMENT 1,797 cc		
YEAR / REG. 2022/02	MILEAGE 24,800 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Station Wagon		
CHASSIS NO. ZRE212-6039683	DIMENSIONS (L X W X H) 450 × 175 × 146 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Front windshield stone chips, interior dirt/stains, exterior small scratches, wheels minor damage/bent, aero parts minor damage/crack, audio hole, scuffs			

ORIGINAL JAPANESE AUCTION SHEET

型式番号 R4 / 2月	メーカー トヨタ	ドア数 5	ボディタイプ ステーションワゴン	評価点 4.5
車種 乗用車・その他 ()	排気量 1800 cc	型式 3BA-ZRE212W	駆動方式 2WD	内装 A・B・C
年 9	月 2	燃料 ガソリン	ディーゼル	後部座席 2WD 4WD
走行 24,800 km	シフト AT	登録番号 ZRE212-6039683	車検 有効	納期 即日
外装色 プラチナホワイトパールマイカ	カラーNo. 000	エンジン 1.8L 4缸	変速機 AT	サドル 黒
内装色 黒	シート 5人	ドア 5	窓 ガラス	ドア ロック
販売店 トヨタ	ディーラー トヨタ	走行 24,800 km	整備 良好	整備 良好
セールスポイント 保証書/純正9インチナビ/衝突安全装置/車線逸脱防止支援システム/シートハーフレザー/ドライブレコーダー/前後LEDヘッドランプ/LEDジャック/Bluetooth接続	修復歴 有・無			
検査記入欄	A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損			
車検 有効	名義中 月 日 まで名義できる方			
車検 有効	ZRE212-6039683			
内装 黒	外装 パール	エンジン 1.8L	変速機 AT	サドル 黒