

2022 Toyota Crown Crossover RS "Advanced"		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5AA-TZSH35	DISPLACEMENT 2,393 cc		
YEAR / REG. 2022/12	MILEAGE 9,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE SUV		
CHASSIS NO. TZSH35-6000219	DIMENSIONS (L X W X H) 493 × 184 × 154 cm		
SALES POINTS			
Alloy Wheels		Leather Seats (Leather)	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
Parking Assist (Auto Steering)		360° Camera	
Navigation System			
INSPECTOR REPORT			
Exterior: Noticeable scratches and dents have been neatly repaired, but minor ones may still remain. Interior: The cabin is clean with few noticeable stains. Repair History: No abnormalities in the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグレード鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 R4/12月	メーカー トヨタ	ドア枚数 4	ボディ形状 SUV/クロカン	評価点 5
車種 クラウンクロスオーバー	グレード RS "Advanced"	車名 5AA-TZSH35	2400	ハイブリッド
用途 自家用	右	駆動方式 4WD	AC	A
年 -	月 -	日 -	走行 9,000 km	重量 Kg
車検 プレミストイボ	カラーNo.	リサイクル料	14,930円	車検番号 TZSH35-6000219
内装 シフト フロア	AT	乗車定員 5人	長さ cm	幅 cm

※車両の事故歴、修理履歴、事故修理の有無等については、別途記載の事故履歴シートを参照してください。
※車両の事故歴、修理履歴、事故修理の有無等については、別途記載の事故履歴シートを参照してください。

グレード鑑定 2022年6月3日 内閣府 鑑定証 E2122RF0304

車両状況の記載

※車両の事故歴、修理履歴、事故修理の有無等については、別途記載の事故履歴シートを参照してください。
※車両の事故歴、修理履歴、事故修理の有無等については、別途記載の事故履歴シートを参照してください。

※車両の事故歴、修理履歴、事故修理の有無等については、別途記載の事故履歴シートを参照してください。
※車両の事故歴、修理履歴、事故修理の有無等については、別途記載の事故履歴シートを参照してください。