

2022 Toyota Granace 2.8 Premium Diesel Turbo

OVERALL

4

EXTERIOR

INTERIOR

-

-

MODEL CODE

3DA-GDH303W

DISPLACEMENT

2,754 cc

YEAR / REG.

2022/01

MILEAGE

103,000 km

DOORS

5

SEATS

6

DRIVETRAIN

2WD (FR)

TRANSMISSION

AT

FUEL

Diesel

STEERING

Right

EXTERIOR COLOR

Black

BODY TYPE

Minivan

CHASSIS NO.

GDH303-1001742

DIMENSIONS (L X W X H)

530 × 197 × 199 cm

SALES POINTS

Alloy Wheels

Power Sliding Doors (Both Sides) (Both...

Pre-Collision Braking

Front Camera

Back Camera

Navigation System

Leather Seats (Leather)

Power Seats (Front)

Adaptive Cruise Control

Side Camera

360° Camera

INSPECTOR REPORT

Minor scratches and small dents

ORIGINAL JAPANESE AUCTION SHEET

車種	トヨタ	グレード	5	ボディタイプ	ミニバンワンボックス	評価点	4
車名	グランエース	2.8 プレミアム ディーゼルターボ	2WD	駆動方式	2WD		
年式	9	月	1	走行	103,000	マイル	000
ボディカラー	ブラック	カラーNo.		エンジン	2.8L	AT	
内装色	ブラック	内装No.		乗車定員	6	人	
左・前・右	左・前・右	ディーラー	走行	16,410	円	税別	
セールスポイント							
本革シート/キースエントリー/A B S /運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/メモリーナビ/フルセグTV/衝突被害軽減ブレーキ/ワンオーナー/ETC/アイドリングストップ/スマートキー/盗難防止システム/オートクルーズコントロール/L E Dヘッドライト/横滑り防止装置 (ESC) /パワーステアリング/シートヒーター/3列シート/ウォークスルー/DVD再生/ミュージックプレイヤー/接続可/CD/全周カメラ/フロントカメラ/サイドカメラ/バックカメラ/後席モニター/障害物センサー/MTモード付き/両側電動スライドドア/定期点検記録簿							
検査記入欄							
小傷 小凹み 薄キズ							
修復歴 有 6							
A キズ B ハミ C 腐食 D 変色 E 変形 F 変質 G 変質 H 変質 I 変質 J 変質 K 変質 L 変質 M 変質 N 変質 O 変質 P 変質 Q 変質 R 変質 S 変質 T 変質 U 変質 V 変質 W 変質 X 変質 Y 変質 Z 変質							
月 日 年							
GDH303-1001742							
車種							
ボディタイプ							
エンジン							
AT							
乗車定員							
6							
左・前・右							
ディーラー							
走行							
16,410							
円							
税別							