

2022 Toyota Hiace Van DX GL Package		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3BF-TRH200V	DISPLACEMENT 1,998 cc		
YEAR / REG. 2022/03	MILEAGE 28,800 km		
DOORS 5	SEATS 6		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Minivan		
CHASSIS NO. TRH200-5051711	DIMENSIONS (L X W X H) 470 × 170 × 199 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Left front dashboard distortion, cargo area scratches and dents, seat burn holes and tears, interior scratches, and front repair history.			

ORIGINAL JAPANESE AUCTION SHEET

R4 / 3月		メーカー トヨタ		ドア枚数 5	ボディ形状 バン	評価点 R																				
車名 ハイエースバン		グレード DX GLパッケージ		駆動区分 2WD																						
走行 28,800 km		インパネ AT																								
外装色 Dブルー		カラーNo. BP4		装備品のみ ORP を記入																						
内装色		6人		AW サンルーフ 革シート																						
左・右		ディーラー 並行		9,550円 預託金 エアロック ABS 4D キーレス																						
セールスポイント																										
ワンオーナー車、社外ナビ・フルセグTV、バックカメラ、ビルドインETC、プリクラッシュセーフティ、レーンディパーチャーアシスト				修復歴 無																						
検査記入欄				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ凹み</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>			A	キズ	U	ヘコみ凹み	B	キズ・ヘコみ	P	色あせ・ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ凹み	B	キズ・ヘコみ	P	色あせ・ボケ	Q	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
左フィンパネヒズミ、荷室キズ凹、シートコゲ穴・スリ切れ、ルーフ内キズ、F修復歴				名義中																						
登録No.				月 日 までにも変更できる方																						
車体番号 TRH200-5051711																										
シリアルNo.																										
FW トヨタ				フレ 外装 小																						
内装 3D				シス ヤブレ コゲ																						
				オーディオ穴																						
長さ cm				幅 cm																						
高さ cm				最大積載量 Kg																						