


2022 Toyota Roomy G		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE 5BA-M900A	DISPLACEMENT 996 cc		
YEAR / REG. 2022/01	MILEAGE 49,731 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Minivan		
CHASSIS NO. M900A-0631507	DIMENSIONS (L X W X H) 370 × 167 × 174 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Both... Navigation System			
Pre-Collision Braking			
INSPECTOR REPORT			
Lower support (screw-on) U, Core support U, Iron powder on exterior, Light scratches on exterior, Minor rust/corrosion on underbody, Interior odor, Interior dirty/stained, Interior trim scratches, Significant headliner stains, Medium carpet burn, Large cigarette burn hole on seat, Touch-up paint marks, Minor scratches on bumper bottom, Minor scratches on mirror, Minor scratches on wheel cover			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 4 1	車 名 ルーミー	ドア+形状 5・HB	グレード G	駆動 4	総合評価点 4
型 式 5BA M900A	排気量 1,000 cc	燃料 ガソリン	車 種 自家用	定員(最大) 5 名	積載量(最大) kg
ミッション IAT	エアコン AAC	カラーNo S28	外 装 色 シルバー	PS 付	PW TV
走行距離 49,731 km	車 検	登録ナンバー	注 意 備 考	車 台 号 号 M900A-0631507	預託金 9,130 円
セールスポイント		特記事項・不具合箇所			
スマートアシスト コーナーセンサー LEDヘッドランプ 両側パワースライドドア ナビ連動ETC		ネジ止ロアサポートU コアサポートU 外装鉄粉付着 外装うすい線キズ 下廻りAU 室内臭い 室内汚れ 室内内張傷 天張汚れ大 カーペット焦げ中 シートタバコ穴大 タッチP跡 バンパー下A ミラーA ホイールカバーA			
注 意 事 項					
W68、パノラミックビューモニター					