

2022 Toyota Sienta 1.5G		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-MXPC10G	DISPLACEMENT 1,490 cc		
YEAR / REG. 2022/10	MILEAGE 26,200 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Green	BODY TYPE Minivan		
CHASSIS NO. MXPC10G-1005721	DIMENSIONS (L X W X H) 426 × 170 × 170 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Both... Adaptive Cruise Control Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Windshield: Scratches, stone chips, cracks, repair marks, needs repair/replacement. Interior: Scratches, dirt, burns, holes, scuffs, tears, rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 令和4 10 月	車名・グレード シエンタ G	2WD 4WD	評価点 (4)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 5BA-MXPC10G	排気量 1500 CC	ドア 5 形状 V
定員 5人	積載 kg	外装 B	内装 B
車歴 自家用	シフト CVT	セールスポイント (正常に機能するものに限りです)	
車検 年 月 (日)	冷房 AAC	キーレススマートキー★ETC★バックモニター	
走行 2万6千200 km	燃料 ガソリン	パワースライドドア (両側)	
色 グリーン	色替 色コード 6X3	装備品 (純正品に限り○をつけてください)	
R券 11,650 円		(P)S (P)W (A)B (A)B AW	
注意事項申告欄		SR ナビ TV カワ	
		新車保証書 後日品	
		有・無	
フロントガラス 内装	キズ・飛石・ヒビ割・リペア跡・X要 キズ・汚レ・コゲ・穴・スレ・キレ・破レ	A-キズ E-エクゴ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済	
車台番号 1005721		型式指定番号 参考	類別区分番号 参考
登録番号		登録年月 参考	備考