


2022 Volkswagen VW T-Roc TDI Style		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3DA-A1DFF	1,968 cc		
YEAR / REG.	MILEAGE		
2022/03	87,519 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
White	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WVGZZZA1ZMV121032	425 × 183 × 159 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Pre-Collision Braking		Adaptive Cruise Control	
Navigation System			
INSPECTOR REPORT			
Partial rust on underbody			

初年度登録		メーカー フォルクスワーゲン		ドア数 5		ボディ形状 SUV/クロカン		年価点																																
R4 / 3月		T-ロック		TDIスタイル		駆動方式 2WD 4WD		4.5																																
車種 自家用・その他 ()		排気量 2000		型式 3DA-A1DFF		通称 型式		内装 A・⑨・C																																
車検 [] 9 年 [] 3 月 / 扶 料 口内にマーク付取付人(車・交換)・(色・色点) (車・交換)		燃料 ガソリン ハイブリッド ()		グレード ハイブリッド		検日通り品 (保証書・取扱説明書 等)																																		
走行 [] 万 円 [] 8 7 , [] 5 1 9		シフト AT		装備品のみ O印 を記入 <table style="width: 100%; text-align: center;"> <tr> <td>()</td> <td>カラーNo. (LC9A)</td> <td>エンジン AD・⑥・AD・WAG・()</td> <td colspan="4"></td> </tr> <tr> <td>()</td> <td>内装色</td> <td>標準装備</td> <td>⑥</td> <td>⑦</td> <td>⑧</td> <td>⑨</td> <td>⑩</td> </tr> <tr> <td>シ</td> <td>左・()</td> <td>輸入 区分</td> <td>⑪</td> <td>⑫</td> <td>⑬</td> <td>⑭</td> <td>⑮</td> </tr> <tr> <td>⑯</td> <td>⑰</td> <td>⑱</td> <td>⑲</td> <td>⑳</td> <td>㉑</td> <td>㉒</td> <td>㉓</td> </tr> </table>						()	カラーNo. (LC9A)	エンジン AD・⑥・AD・WAG・()					()	内装色	標準装備	⑥	⑦	⑧	⑨	⑩	シ	左・()	輸入 区分	⑪	⑫	⑬	⑭	⑮	⑯	⑰	⑱	⑲	⑳	㉑	㉒	㉓
()	カラーNo. (LC9A)	エンジン AD・⑥・AD・WAG・()																																						
()	内装色	標準装備	⑥							⑦	⑧	⑨	⑩																											
シ	左・()	輸入 区分	⑪							⑫	⑬	⑭	⑮																											
⑯	⑰	⑱	⑲	⑳	㉑	㉒	㉓																																	
ボワイト		()																																						
()		人																																						
シ		左・()		輸入 区分																																				

13,450円

セールスポイント

メーカーナビ、純正17インチAW、バックカメラ、LED
ヘッドランプ、ブラインドスポットモニター、レーダー
クルーズコントロール



検 査 部

有・⑨

検査記入欄																															
下廻り一部サビ																															
<table style="width: 100%; text-align: center;"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>へこみ</td> <td>サビ</td> <td>目</td> <td>キズ・へこみ</td> <td>P</td> <td>色あせ・サビ</td> <td>G</td> <td>ガラスキズ</td> </tr> <tr> <td>W</td> <td>補修跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> <td></td> </tr> </table>										A	キズ	U	へこみ	サビ	目	キズ・へこみ	P	色あせ・サビ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済	
A	キズ	U	へこみ	サビ	目	キズ・へこみ	P	色あせ・サビ	G	ガラスキズ																					
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																						
登録年 [] 月 [] 日 まで(に名義変更)																															
車体 番号 WGZZZA1ZMV121032																															
<table style="width: 100%; text-align: center;"> <tr> <td>FW</td> <td>①</td> <td>②</td> <td>③</td> <td>④</td> <td>⑤</td> <td>⑥</td> <td>⑦</td> <td>⑧</td> <td>⑨</td> <td>⑩</td> </tr> <tr> <td>内装</td> <td>⑪</td> <td>⑫</td> <td>⑬</td> <td>⑭</td> <td>⑮</td> <td>⑯</td> <td>⑰</td> <td>⑱</td> <td>⑲</td> <td>⑳</td> </tr> </table>										FW	①	②	③	④	⑤	⑥	⑦	⑧	⑨	⑩	内装	⑪	⑫	⑬	⑭	⑮	⑯	⑰	⑱	⑲	⑳
FW	①	②	③	④	⑤	⑥	⑦	⑧	⑨	⑩																					
内装	⑪	⑫	⑬	⑭	⑮	⑯	⑰	⑱	⑲	⑳																					