

2023 Audi A3 Sportback 30TFSI S line		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GYDLA	DISPLACEMENT 999 cc		
YEAR / REG. 2023/09	MILEAGE 6,900 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Hatchback		
CHASSIS NO. WAUZZZGY7PA139668	DIMENSIONS (L X W X H) 450 × 182 × 143 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Adaptive Cruise Control Back Camera		Leather Seats Pre-Collision Braking Parking Assist (Auto Steering) Navigation System	
INSPECTOR REPORT			
Interior dirt, stains, tears, burns, burn holes, audio holes, scuffs			

初年度登録	メーカー アウディ	ドア数 5	ボディ形状 コンパクトハッチバック	呼称名 9																																																																																
R5 / 9月	車名 A 3	グレード Sフォーテック 30 TFSI Sライン	駆動方式 2WD 4WD	4.5																																																																																
車種 自動車・その他（ ）	排気量 1000 CC	型式 GYDLA	運転形式	内装 A・C・G																																																																																
年次 - 年 - 月 - 日	燃料 ガソリン	ディーゼル	後付選り品（保証書・取扱説明書等）																																																																																	
走行 □□ □ □ 6,900 km	シフト フロア 7 AT																																																																																			
外装色 グレイシアークワートメタリック	カラーNo. AGD・AAD・WAD・（ ）	新着商品のO印を記入																																																																																		
()	内装色 5人	サンルーフ																																																																																		
左・右・後 G - 走行 1,433円	リサイクル料	エアロパック																																																																																		
セーレスポイント																																																																																				
本革シートパワーシート/ワンオーナー/バックカメラ横滑り防止装置（ESC）/運転席エアバック/座席防しシステム/スマートキー/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/フルセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリingsストップパーボ/シートヒーター																																																																																				
検査記入欄																																																																																				
検査項目 有：(A) <table border="1"> <thead> <tr> <th>検査項目</th> <th>結果</th> <th>検査項目</th> <th>結果</th> <th>検査項目</th> <th>結果</th> <th>検査項目</th> <th>結果</th> <th>検査項目</th> <th>結果</th> </tr> </thead> <tbody> <tr> <td>A</td> <td>○</td> <td>N</td> <td>○</td> <td>B</td> <td>○</td> <td>O</td> <td>○</td> <td>C</td> <td>○</td> </tr> <tr> <td>D</td> <td>○</td> <td>P</td> <td>○</td> <td>E</td> <td>○</td> <td>Q</td> <td>○</td> <td>F</td> <td>○</td> </tr> <tr> <td>G</td> <td>○</td> <td>R</td> <td>○</td> <td>H</td> <td>○</td> <td>S</td> <td>○</td> <td>I</td> <td>○</td> </tr> <tr> <td>J</td> <td>○</td> <td>T</td> <td>○</td> <td>K</td> <td>○</td> <td>U</td> <td>○</td> <td>L</td> <td>○</td> </tr> <tr> <td>M</td> <td>○</td> <td>V</td> <td>○</td> <td>N</td> <td>○</td> <td>W</td> <td>○</td> <td>O</td> <td>○</td> </tr> <tr> <td>P</td> <td>○</td> <td>X</td> <td>○</td> <td>A</td> <td>○</td> <td>Y</td> <td>○</td> <td>B</td> <td>○</td> </tr> <tr> <td>Q</td> <td>○</td> <td>Z</td> <td>○</td> <td>C</td> <td>○</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table> 車検合格 MAUZGGY7P A139668					検査項目	結果	検査項目	結果	検査項目	結果	検査項目	結果	検査項目	結果	A	○	N	○	B	○	O	○	C	○	D	○	P	○	E	○	Q	○	F	○	G	○	R	○	H	○	S	○	I	○	J	○	T	○	K	○	U	○	L	○	M	○	V	○	N	○	W	○	O	○	P	○	X	○	A	○	Y	○	B	○	Q	○	Z	○	C	○				
検査項目	結果	検査項目	結果	検査項目	結果	検査項目	結果	検査項目	結果																																																																											
A	○	N	○	B	○	O	○	C	○																																																																											
D	○	P	○	E	○	Q	○	F	○																																																																											
G	○	R	○	H	○	S	○	I	○																																																																											
J	○	T	○	K	○	U	○	L	○																																																																											
M	○	V	○	N	○	W	○	O	○																																																																											
P	○	X	○	A	○	Y	○	B	○																																																																											
Q	○	Z	○	C	○																																																																															