

2023 Audi Audi A6 40 TDI quattro S line Diesel Turbo 4WD		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 3CA-F2DFBF	DISPLACEMENT 1,968 cc		
YEAR / REG. 2023/12	MILEAGE 13,800 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Sedan		
CHASSIS NO. WAUZZZF22PN089042	DIMENSIONS (L X W X H) 495 × 189 × 143 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Adaptive Cruise Control Front Camera Back Camera Audi Sound System (180W, 10 speakers)		Leather Seats Pre-Collision Braking Parking Assist (Auto Steering) Side Camera Navigation System	
INSPECTOR REPORT			
Front glass: Scratches, stone chips, cracks, repair marks, replacement needed. Interior: Scratches, stains, burns, holes, scuffs, tears.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 令和5 12月	車名・グレード アウディ A6 40TDIクワトロSラインパッケージ	2WD 4WD	評価点 (4.5)		
ディーラー・並行 モデル年式 年 ハンドル 左	型式 3CA-F2DFBF	排気量 2000 CC	ドア 4 定員 5人 外装 B 内装 A		
車庫 自家用	シフト FAT	セールスポイント (正常に機能するものに限りです)			
車検 令和8年 12月 (日)	冷房 WAC	キーレススマートキーバックモニター			
走行 1万3千800 km	燃料 その他	装備品 (純正品に限り○をつけてください)			
色 パール	色コード マイ	(PS) (PW) (ABS) (ESP) (AW) (SR) (ナビ) (TV) (カメラ)			
R券 16,300 円		新車保証書 有・無			
注意事項申告欄		後日品			
フロントガラス キズ・飛石・ヒビ割・リペア跡・X要 内装 キズ・汚レ・コゲ・穴・スレ・キレ・破レ		A1 スケア			
車台番号 PN089042	A-キズ E-エクボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済				
登録番号 広島 302 と 971	型式指定番号 登録区分番号 車検有効期 備考				