

2023 Audi Audi Q8 55 TFSI quattro S line		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
F1DCBA	2,994 cc		
YEAR / REG.	MILEAGE		
2023/12	29,100 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WAUZZZF11PD039309	501 × 200 × 169 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Leather Seats		Power Tailgate	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Front Camera	
Side Camera		Back Camera	
Navigation System		Bang & Olufsen 3D Sound System (730...	
INSPECTOR REPORT			
Front windshield stone chip, left mirror scratch			

年式/月	年式	グレード	ボディ/塗装	年式	SUV/クロカン	評価点
R5 / 12月	アウディ	Q 8	55 TFSI クワトロ	55 TFSI クワトロ	55 TFSI クワトロ	4
車種	用途等・その他 ()	排気量	3000	型式	F1DCBA	内装
車検	8 年 1 2 月	燃料	ガソリン	ディーゼル	検定番号 (保証書・事故証明等)	A ⑨・C
走行	29,100 km	シフト	フロア 8 AT			
外装色	パールホワイト	エンジン	Q8・A8・WAG・()			
ミストブラックメタリック	()	内装色	5人			
()	左・R 前	後	17,970円・			
セルスポイント						
本革シート/パワーシート/ワンオーナー/バックカメラ/横滑り防止装置 (ESC) /運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/メモリーナビ/フルセグTV /衝突被害軽減ブレーキ/衝突安全ボディ /4WD /アイドリングストップ/ターボシートヒーター/シートエアコン/電動リアゲート/全周囲カメラ/フロントカメラ/サイドカメラ						
検査入欄						
フロントウィンドウ飛び石 左ミラー僅						
年式 W 新車納付 S サビ C 腐食 X 交換済 XX 交換済 車検月 月 日 までに各費で検定済 型式番号 WAUZZZF11P0393909						
FW	トボ石	傷A	ワレ	汚損	小	大
内装	ヨレ	シミ	ヤブレ	コガ	コガ	スレ