


2023 BMW 1series M135i xDrive		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
7L20	1,998 cc		
YEAR / REG.	MILEAGE		
2023/09	680 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBA7L120607N01097	436 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels		Power Tailgate	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Parking Assist (Auto Steering)	
Back Camera		Navigation System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R5 / 9月	メーカー BMW	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	登録点 5
車名 1シリーズ	グレード M135i xDriveアドバンスDPKG	駆動方式 2WD	登録区分 4WD	
車種 自動車	用途 自家用・その他	年式 2000	型式 CG	7L20
登録 - - - 月 / - -	燃料 ガソリン	ディーゼル	後日送り品 (取替・取替等)	
走行 680 km	フロア 8 AT	スペアキー		
外装色 ホワイト	カラーNo.	新車のみ O印 を記入		
内装色 ()	エンジン QD・AAG・WAG・()	乗車定員 5人	サンルーフ	革シート
左・右・中 左・中・右	デモ・走行	15,830円	エレクトロニクス	TV
セールスポイント パワーシート/ワンオーナー/バックカメラ/横滑り防止装置 (ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/HDDナビ/衝突被害軽減ブレーキ/4WD/アイドリングストップ/ターボ/シートヒーター/電動リアゲート/ミュージックプレイヤー接続可				
検査記入欄		修復歴 有・無		
		A 今文 U ヘッドランプ B キズへこみ P 色あせ・汚れ Q ガラスキズ W 修理跡 S サビ C 腐食 X 交換品 YX 交換済		
		登録No. 月 日 までに名変せざる方		
		車体番号 WBA7L120607N01097		
内装 フロア	トビ石	備え	フレ	外装 小 A・U A・曲 A・フレ
内装 フロア	シス	ヤブレ	コサ	コサ穴
内装 フロア	スレ	オーディオ	スレ	スレ
内装 フロア	スレ	スレ	スレ	スレ