

2023 BMW BMW X1 xDrive 20d X Line

OVERALL

5

EXTERIOR

INTERIOR

-

-

MODEL CODE

3CA-42EG20

DISPLACEMENT

1,995 cc

YEAR / REG.

2023/12

MILEAGE

11,000 km

DOORS

5

SEATS

5

DRIVETRAIN

4WD

TRANSMISSION

AT

FUEL

Hybrid (Diesel)

STEERING

Right

EXTERIOR COLOR

Silver

BODY TYPE

SUV

CHASSIS NO.

WBA42G0X05X80717

DIMENSIONS (L X W X H)

450 × 184 × 165 cm

SALES POINTS

Alloy Wheels

Power Tailgate

Pre-Collision Braking

Parking Assist (Auto Steering)

Side Camera

Navigation System

Roof Rails

Power Seats (Front)

Adaptive Cruise Control

Front Camera

Back Camera

INSPECTOR REPORT

AIS inspected. Minor scuff on steering wheel and console.

ORIGINAL JAPANESE AUCTION SHEET

R5 / 12月		BMW X 1		5 xDrive 20d xライン		5	
白家用・その他 ()		2000	3CA-42EG20	2WD		A・B・C	
8年12月		扶養	ディーゼル	後日選用品 (電装・取付・明等)			
11月500		フロア 7 AT					
スペースシルバー		カラーNo. C67	新車品のみ O印 を記入				
()		5人	サンルーフ 革シート				
左・前・後・右		17,210円	エレクトロニクス TV				
セールスポイント							
キーレスエントリー/A B S / 運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/H D D ナビ/衝突被害軽減ブレーキ/4WD/ワンオーナー/ETC/アイドリングストップ/スマートキー/盗難防止システム/オートクルーズコントロール/L E D ヘッドライト/横滑り防止装置 (E S C) / パワーステアリング/シートヒーター/ミュージックプレイヤー/接続可/全周周知カメラ/フロントカメラ/サイドカメラ/バックカメラ/障害物センサー/パーキングアシスト							
特記事項							
スペースシルバー センサテックブラック Xライン 18AW ワンオーナー マット無し Sキ有							
検査記入欄							
AIS 検査済 ハンドル擦れ小 コンソールA小							
A キズ B ハコボケ C キズヘコ D 色あせ・汚れ E ガラスキズ W 腐食 G サビ H 変色 I 変形 J 変色 K 変色 L 変色 M 変色 N 変色 O 変色 P 変色 Q 変色 R 変色 S 変色 T 変色 U 変色 V 変色 W 変色 X 変色 Y 変色 Z 変色							
WBA42G0X05X80717							
トヨタ 日産 三菱 本田 鈴木 富士 日野 五十鈴 日産 三菱 本田 鈴木 富士 日野 五十鈴							