

2023 BMW_Mini BMW Mini Clubman Cooper D Clubman		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-BB20M	DISPLACEMENT 1,995 cc		
YEAR / REG. 2023/09	MILEAGE 23,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Station Wagon		
CHASSIS NO. WMW72BB0502U84136	DIMENSIONS (L X W X H) 428 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels Back Camera		Leather Seats Navigation System	
INSPECTOR REPORT			
Tire cracks, minor seat wrinkles, minor driver's seat wear, minor carpet wear.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R5 / 9月	メーカー MINI MINI	ドア枚数 5	ボディ形状 ステーションワゴン	評価値 4.5
車種 自家用・その他 ()	排気量 2000 CC	型式 3DA-BB20M	通称 2WD	内装 A・B・C
車検 - 年 - 月 / 日	燃料 ガソリン	変速機 オートマチック	後付選り品 (保証書・取扱説明書 等)	
走行 23,000 km	フロア 8 AT			
外装色 インディアンサマーレッド	カラーNo. AG・AG・WAG・ ()	装備品のみ O印 を記入		
内装色 ()	乗車定員 5 人	サンルーフ	ナビ	その他
左・前・後 左・前・後	走行 15,950円	ナビ	TV	その他
セールスポイント 本革シート/キーレスエントリー/ABS/運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/メモリーナビ他/衝突被害軽減ブレーキ/ETC/スマートキー/盗難防止システム/オートクルーズコントロール/横滑り防止装置 (ESC) /シートヒーター/バックカメラ/障害物センサー/パーキングアシスト/MTモード付き				
検査記入欄 タイヤヒビ/シートしわ小/運転席すれ小/カーペットすれ小				
修復歴 有・無				
A キズ U ヘビイキズ B キズヘビイ P 色あせキズ G ガラスキズ W 補修跡 S ヤビ C 腐食 X 交換部 YX 交換部				
登録No. 月 日 までに変更できる方 名変更				
車体番号 WMW72BB0502U84136				
FW トピ石 備A フレ 外装 小 A・U A・曲 A・フレ シリアル No.				
内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ 車種 長さ cm 幅 cm 高さ cm 最大積重量 Kg				