

2023 BMW_Mini MINI OTHER 2.0 Cooper D Crossover ALL4 Premium+Pkg		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3DA-42BT20	1,995 cc		
YEAR / REG.	MILEAGE		
2023/11	33,151 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Other		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WMW62BT0403R87130	431 × 182 × 159 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Power Tailgate		Pre-Collision Braking	
Back Camera		Cruise Control	
360° Camera		Navigation System	
INSPECTOR REPORT			
Exterior: Minor scratches, dents, unevenness. Wheel scratches. Left side aero scratches. Trim wrinkles, scuffs, scratches. Trunk/cargo area scuffs, scratches, dirt. Dashboard scuffs, scratches, dirt. Front windshield: Scratches, stone chips, cracks, repair marks, needs replacement. Interior: Scratches, dirt, burns, holes, scuffs, tears, rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 令和5 11月	車名・グレード BMWミニクロスオーバー クーパードクロスオーバーオール4	2WD (4WD)	評価点 (4)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 3DA-42BT20	排気量 2000 CC	ドア 5 形状 木
定員 5人	積載 kg	外装 B	内装 B
車種 自家用	シフト FAT	セールスポイント (正常に機能するものに限ります)	
車検 年 月 (日)	冷房 AAC	スマートキー・ETC	
走行 3万3千151 km	燃料 軽油	メモリーナビ、バックカメラ、Bluetooth	
色 パール2	色替 マイ	諸備品 (純正品に限り○をつけてください)	
R券 16,320 円		(PS) (PW) (BS) (AB) (W) SR ナビ TV カワ	
注意事項申告欄		新車保証書 有・無	
外装 小A・小U ホイール キズ 左サイドエアロキズ トリムシワスレキズ 荷室スレキズヨゴレ ダッシュスレキズヨゴレ		車台番号 03R87130	
フロントガラス 内装 キズ・汚レ・コゲ・穴・スレ・キレ・破レ		登録番号	
車台番号 03R87130		型式 19918	
登録番号		識別区分番号 0101	
		長さ 431	
		幅 182	
		高さ 159	

スレ