

2023 CHRYSLERJEEP JEEP Wrangler UNLTD Sahara		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE JL20L	DISPLACEMENT 1,995 cc		
YEAR / REG. 2023/08	MILEAGE 42,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. 1C4HJXLN1PW561492	DIMENSIONS (L X W X H) 487 × 190 × 185 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Front Camera Back Camera Alpine Premium 9-speaker Sound System...		Leather Seats (Leather) Adaptive Cruise Control Side Camera Navigation System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

車種 R5	メーカー クライスラー・ジープ	ドア数 5	ボディ形状 SUV/クロカン	評価点 4.5
8月	車名 ジープ・ラングラーアンリミテッド	グレード サハラ	駆動方式 2WD	
車庫 自家用・その他 ()	排気量 2000 cc	型式 JL20L	登録区分 A・⑤・C	
年 -	月 -	日 -	ディーゼル -	後付選用品 (保証書・取扱説明書等)
走行 42,000 km	シフト フロア 8 AT	燃料 ガソリン	エアコン ④・AAG・WAG・()	
外装色 BLACK	カラーNo. ()	内装色 ()	乗車定員 5人	新着品のみ・O印を記入
左・前 ①	右・後 ②	左・前 ③	右・後 ④	サンルーフ ⑤
左・前 ⑥	右・後 ⑦	左・前 ⑧	右・後 ⑨	その他 ⑩
セールスポイント 本車シート/バックカメラ/ETC/横滑り防止装置 (ESC) /運転席エアバック/スマートキー/キースタート/リアB/S/助手席エアバック/サイドエアバック/メモリーナビ/フルセグTV/衝突被害軽減ブレーキ/4WD/アイドリングストップ/ターボ/フロントカメラ/サイドカメラ				
検査記入欄 A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損 名義中 月 日 まで 1C4HJXLN1PW561492				
内装 トビ石	外装 メタリック	小 A・U	中 A・U	大 A・U
内装 メタリック	外装 メタリック	小 A・U	中 A・U	大 A・U