

2023 CITROEN CITROEN Berlingo Trico		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3DA-K9CYH01	1,498 cc		
YEAR / REG.	MILEAGE		
2023/07	22,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
White	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
VR7ECYHZ3NJ784994	441 × 185 × 185 cm		
SALES POINTS			
Alloy Wheels		Glass Roof	
Roof Rails		Pre-Collision Braking	
Adaptive Cruise Control		Side Camera	
Back Camera			
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R5 / 7月	メーカー シトロエン ベルランゴ	ドア数 5	ボディ形状 コンパクトハッチバック	評価点 4.5
車種 3DA-K9CYH01	グレード トリコ	駆動方式 2WD	駆動区分 4WD	内装 A・B・C
車検 - - - 年 / 月 / 日	排気量 1500 cc	型式 3DA-K9CYH01	通称 型式	内装 A・B・C
走行 22,000 km	燃料 ガソリン	変速機 AT	後日送り品 (修理・取替・スペアキー等)	
外装色 ブロンズ	カラーNo. A00	エンジン QD・AAG・WAG・()	保証書・取替・スペアキー後日送付	
内装色 ()	乗車定員 5人	PS	PW	AW
左・右・後 左・右・後	15,910円	エアバック	ABS	ナビ
セールスポイント 特別仕様車・ガラスルーフ・360度カメラ・ドラレコ・オートライト・LKA・BSA・衝突軽減ブレーキ・追従クルコン・Bluetooth・ミラーリンク・ディスプレイオーディオ・ETC・パドル・R16	修復歴 有・無			
特記事項 ABSカーセンサー認定済み 4.5点 スペアキー有り	A 今文 U ヘッドランプ B キズ・へこみ P 色あせ・汚れ Q ガラスキズ W 修理跡 S サビ C 腐食 X 交換品 YX 交換済			
検査記入欄	車検No. 月 日 までに検査できる方 車体番号 VR7ECYHZ3NJ 784994			
内装 トヨタ シネ ヤブ コガ コガ オーディー	外装 小 A・U A・曲 A・フレ	ホイール エアロ A・フレ	シリアル No.	重量 cm cm cm Kg