

2023 Honda Civic 5HB Hybrid e:HEV		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
6AA-FL4	1,993 cc		
YEAR / REG.	MILEAGE		
2023/03	18,300 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
FL4-1003244	455 × 180 × 142 cm		
SALES POINTS			
Alloy Wheels		Power Seats (Front)	
Pre-Collision Braking		Adaptive Cruise Control	
Back Camera		Navigation System	
Bose Premium Sound System (12 Spea...			
INSPECTOR REPORT			

年式 R5 / 3月 メーカー ホンダ 車名 シビックハイブリッド ドア数 5 グレード eHEV 評価点 コンパクトハッチバック 2WD 4WD 評価点 4.5																																											
車種 自家用・その他 ()		排気量 2000	型式 CC 6AA-FL4	燃費 型式	内装 A・B・C																																						
年式 1 0 年 3 月 / 抹消		製 国 日本	ディーゼル ハイブリッド ()																																								
走行 1 8 年 3 月 0 日		AT																																									
外装色 クリスタルブラック・パール カラーNo. ()		エアコン Q・A・G・W・G・ ()																																									
内装色 ()		乗車定員 5人																																									
シート 左・(裏) 右・(表)		輸入 国 ディーラー 走行 日走行距離 11,960km		車種別 エアロック																																							
セールスポイント 保証書純正5年10万kmホンダセンシングシートヒーター 前席/後席逸脱防止支援システム/シート ハーフレザークロノグラフ LED A/S Bジャック/Bluetooth接続																																											
検査記入欄																																											
※写真																																											
検査結果 有・無																																											
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>へこみ/サレ</td> <td>B</td> <td>キズ/へこみ</td> <td>P</td> <td>色あせ/サレ</td> <td>G</td> <td>ガラス/キズ</td> </tr> <tr> <td>W</td> <td>補修跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換歴</td> <td>XX</td> <td>交換歴</td> </tr> <tr> <td colspan="9"> 登録地 月 日 ※名義と異なる場合は </td> </tr> <tr> <td colspan="9"> 車体番号 FL4-1003244 </td> </tr> </table>						A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/サレ	G	ガラス/キズ	W	補修跡	S	サビ	C	腐食	X	交換歴	XX	交換歴	登録地 月 日 ※名義と異なる場合は									車体番号 FL4-1003244								
A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/サレ	G	ガラス/キズ																																		
W	補修跡	S	サビ	C	腐食	X	交換歴	XX	交換歴																																		
登録地 月 日 ※名義と異なる場合は																																											
車体番号 FL4-1003244																																											
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>PW</td> <td>パワ ウインド</td> <td>備A</td> <td>フレ</td> <td>外装</td> <td>小 ① ②</td> <td>ホイ ール</td> <td>エアロ パーツ</td> <td>シリアル No.</td> </tr> <tr> <td>内装</td> <td>③</td> <td>シロ</td> <td>ヤレ</td> <td>コガ</td> <td>コガ</td> <td>オキ</td> <td>オキ</td> <td>最大積載量</td> </tr> </table>						PW	パワ ウインド	備A	フレ	外装	小 ① ②	ホイ ール	エアロ パーツ	シリアル No.	内装	③	シロ	ヤレ	コガ	コガ	オキ	オキ	最大積載量																				
PW	パワ ウインド	備A	フレ	外装	小 ① ②	ホイ ール	エアロ パーツ	シリアル No.																																			
内装	③	シロ	ヤレ	コガ	コガ	オキ	オキ	最大積載量																																			