

2023 Honda N-BOX L		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JF3	658 cc		
YEAR / REG.	MILEAGE		
2023/08	18,431 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF3-5332314	340 × 148 × 179 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Drive...		Pre-Collision Braking	
Adaptive Cruise Control		Navigation System	
INSPECTOR REPORT			
Main equipment OK. Minor scratches on door trim, console, cargo area, and glove box. Light exterior scratches. Tires cracked.			

ORIGINAL JAPANESE AUCTION SHEET

年式 R5 / 8月	メーカー ホンダ	ドア枚数 5	ボディ形状 軽四	評価点 4
車名 N-BOX L	グレード 2WD	駆動方式 4WD		
車種 自家用・その他 ()	排気量 660 cc	型式 JF3	燃料 ガソリン	内装 A・B・C
年 9	月 8	走行 18,431 km	燃料 ハイブリッド ()	備考 A・B・C
走行 18,431 km	燃料 ハイブリッド ()	インパネ	AT	
外装色 クリスタルブラックパール	カラーNo. AAG・WAG・()	エアコン	AW	サンルーフ
内装色 ()	乗車定員 4人	AW	サンルーフ	高シート
小 左・右	大 左・右	8,550円	TV	ス
セールスポイント				
バックカメラ/ETC/横滑り防止装置 (ESC) /運転席エアバック/スマートキー/キーレスエントリー/ABS/サイドエアバック/メモリーナビ他衝突被害軽減ブレーキ/アイドリングストップ/オートクルーズコントロール/シートヒーター/ベンチシート/両側電動スライドドア				
検査記入欄				
※主要設備確認OK 「ドア内張りA<小> コンソールA<小> 外装薄緑キズ タイヤヒビ 両面A<小> グローブボックスA<小>				
A キズ U ヘッドランプ B キズ・ヘッド P 色あせ・汚れ Q ガラスキズ W 雨漏り S サビ C 腐食 X 交換部 YX 交換部 売却No. 月 日 までに希望できる方 車体番号 JF3-5332314				
FW	トボ石	傷A	フレ	外装
内装	コゴレ	シミ	ヤブレ	コガ
				コガ穴
				オーディオ穴
				スレ
				車輪
				高さ
				高さ
				最大積載量
				kg