


2023 Honda Step Wagon Air		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-RP6	DISPLACEMENT 1,496 cc		
YEAR / REG. 2023/02	MILEAGE 44,189 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Minivan		
CHASSIS NO. RP6-1108329	DIMENSIONS (L X W X H) 480 × 175 × 184 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking 360° Camera		Power Sliding Doors (Both Sides) (Both... Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Light dirt inside the cabin.			

ORIGINAL JAPANESE AUCTION SHEET

R5 / 2月		ホンダ		ドア数 5	ボディ形状 ミニバン/ワンボックス	評価値 4.5
車名 ステップワゴン		グレード エアー		駆動区分 4WD	4WD	
車種 自家用・その他 ()	排気量 1500 CC	型式 5BA-RP6	変換形式	内装 A・⑥・C		
年 10年	月 2月	走行 14,189 km	燃料 無鉛ハイブリッド	ディーゼル	後日選り品 (緑書・取付印等)	
走行 14,189 km	インパネ	AT				
外装色 パール	カラーNo. NH883P	AG・⑥・WAG・()	装備品のみ O印 を記入			
内装色 ()	乗車定員 7人	⑤	⑥	⑦	サンルーフ	革シート
⑧ 左・⑨ 輸入車	ディーラー	走行 12,310 km	⑩ 無	⑪ エアロック	⑫	⑬ キーレス
セールスポイント ★ホンダセンシング★純正11インチナビ★フルゼグTV★純正15.6インチフリップダウンモニター★マルチビューモニター★ETC★スマートキー★プッシュスタート★LEDヘッドライト★レザー調シートカバー★アダプティブクルーズコントロール★ステアリングスイッチ★前後ドライブレコーダー★両側パワースライドドア★						
検査記入欄 ルーム内薄汚れ			修復歴 有・⑭			
A キズ U ヘッドランプ B キズ・ヘッド P 熱帯セーバー Q ガラスキズ			W 補修品 S サイズ C 腐食 X 交換品 YX 交換品			
登録No. 月 日 まで名義できる方			名義中			
車体番号 RP6-1108329						
⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺	シリアル No.					
① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺	長さ 幅 高さ 最大積載量 kg					