

2023 Jeep Compass Limited		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3BA-M624	DISPLACEMENT 2,359 cc		
YEAR / REG. 2023/05	MILEAGE 45,450 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE SUV		
CHASSIS NO. MCANJRCB3NFA97878	DIMENSIONS (L X W X H) 442 × 181 × 164 cm		
SALES POINTS			
Alloy Wheels Roof Rails Power Tailgate Pre-Collision Braking Parking Assist (Auto Steering) Side Camera 360° Camera Alpine 506W 9-speaker Premium Sound...		Sunroof Leather Seats (Leather) Power Seats (Front) Adaptive Cruise Control Front Camera Back Camera Navigation System	
INSPECTOR REPORT			
AIS inspected, main equipment confirmed OK. Minor wrinkles on driver's seat, minor scratches on door trim and cargo area trim. Minor scuff on steering wheel, minor scratches on console. Evidence of BO repair. Stone chips on front area and front glass. Hood shows signs of removal/reinstallation.			

ORIGINAL JAPANESE AUCTION SHEET

R5 / 5月	メーカー クライスラー・ジープ	ドア数 5	ボディ形状 SUV/クロカン	評価点 4.5
車種 自家用・その他 ()	排気量 2400 cc	型式 3BA-M624	登録区分 2WD	内装 A・⑤・C
年 月 日	燃料 無鉛ハイブリッド	ディーゼル	後付選用品 ()	
走行 45,450 km	フロア 9 AT	スペアキー		
外装色 パールホワイトトリコト	カラーNo. ()	エアコン ()	新選用品のみ O印 を記入	
内装色 ()	乗車定員 5 人	安全装置 ()	サドルアップ	エアロ
走行 左・前・後・左・右	走行 15,040 km	エンジン	TV	オーディオ
セールスポイント				
サンルーフ LEDライト 後期型 革Pシート 全周囲 AppleCarPlay ACC ステアリングヒーター シートヒーター レンキアシスト Fカメラ Sカメラ Bカメラ				
検査記入欄				
★ A I S 検査済 ☆ 主要装備確認 O K 運転席しわ小 ドア内張A小 荷室内張りA小 ハンドル握れ小 コンソールA小 BO修理跡 フロント通り飛び石 ボンネット脱着跡 Fガラス飛び石小				
車検番号 MCANJ RCB3NFA97878				
内装 ()	シス	サブレ	コグス	オーディオ
身長 cm	体重 cm	最大積載量 kg		