

| 2023 Land Rover Defender5D 110 S D300                                                                                                                       |                                              | OVERALL                                                                                               |          |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|-------------------------------------------------------------------------------------------------------|----------|
|                                                                                                                                                             |                                              | 4.5                                                                                                   |          |
|                                                                                                                                                             |                                              | EXTERIOR                                                                                              | INTERIOR |
|                                                                                                                                                             |                                              | -                                                                                                     | -        |
| MODEL CODE<br>3CA-LE72WCB                                                                                                                                   | DISPLACEMENT<br>2,993 cc                     |                                                                                                       |          |
| YEAR / REG.<br>2023                                                                                                                                         | MILEAGE<br>19,500 km                         |                                                                                                       |          |
| DOORS<br>5                                                                                                                                                  | DRIVETRAIN<br>4WD                            |                                                                                                       |          |
| TRANSMISSION<br>AT                                                                                                                                          | FUEL<br>Hybrid (Diesel)                      |                                                                                                       |          |
| STEERING<br>Right                                                                                                                                           | EXTERIOR COLOR<br>Black                      |                                                                                                       |          |
| BODY TYPE<br>SUV                                                                                                                                            |                                              |                                                                                                       |          |
| CHASSIS NO.<br>SALEA7AWXP2187205                                                                                                                            | DIMENSIONS (L X W X H)<br>494 × 199 × 197 cm |                                                                                                       |          |
| SALES POINTS                                                                                                                                                |                                              |                                                                                                       |          |
| Alloy Wheels<br>Power Seats (Front)<br>Adaptive Cruise Control<br>Side Camera<br>Navigation System                                                          |                                              | Roof Rails<br>Pre-Collision Braking<br>Front Camera<br>Back Camera<br>Sound System (180W, 6 Speakers) |          |
| INSPECTOR REPORT                                                                                                                                            |                                              |                                                                                                       |          |
| Stone chips on front, left front fender repainted (repair for scratch when exiting garage), door has fine scratches and minor scratches. Interior is dirty. |                                              |                                                                                                       |          |

[illegible]