

2023 Lexus LS Hybrid 500h Executive		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GVF55	DISPLACEMENT 3,456 cc		
YEAR / REG. 2023/06	MILEAGE 81,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Sedan		
CHASSIS NO. GVF55-6008460	DIMENSIONS (L X W X H) 524 × 190 × 146 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Adaptive Cruise Control Front Camera Back Camera Navigation System		Leather Seats Pre-Collision Braking Parking Assist (Auto Steering) Side Camera 360° Camera Mark Levinson Reference 3D Surround ...	
INSPECTOR REPORT			
Exterior: Major scratches and dents have been neatly repaired, but minor scratches and dents may still remain. Interior: Some noticeable stains are present in parts. Accident history: No abnormalities in the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のカー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 R5 6月	メーカー レクサス	ドア枚数 4	ボディ形状 セダン	評価点 4.5
車名 L S	グレード 500h	エグゼクティブ		
車種 自家用	右	GVF55	3500	ハイブリッド
年 -	月 -	日 -	4WD	AC
走行 81,000	カラーNo.	リサイクル料	19,560円	車体番号 GVF55-6008460
先 グランドブラックガラスフレック	シフト フロア	AT	5人	重量 1,900kg
後 ()	内装 -	外装 -	CTD	CTD

検口送り足
(保証書・取扱説明書等)

整備
エンジン
エアコン
サドル
シート
セーリングポイント

常設員記入欄

ボクサーレベルに関する注意事項
※ボクサーレベルの点検
※ボクサーレベルの点検
※ボクサーレベルの点検

クオリティグレード説明
外装気になるようなキズや凹みがあった場合は納品に補償済みですが、小さなキズや凹みが残っている場合もあります。
内装気になる汚れ等が、部分的にあります。
傷痕: 傷痕部位に異変はありません。

車両状態の図解
車両状態の図解
車両状態の図解