

2023 LX LX600		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3BA-VJA310W	3,444 cc		
YEAR / REG.	MILEAGE		
2023/03	64,069 km		
DOORS	SEATS		
5	7		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
VJA310-4022623	510 × 199 × 189 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Power Tailgate		Leather Seats (Semi-aniline Leather)	
Adaptive Cruise Control		Navigation System	
Lexus LX Premium Sound System (10 s...			
INSPECTOR REPORT			
Seat wear, minor trim imperfections (Trim A), light interior stains, minor exterior imperfections (Exterior A), stone chips around the front, touch-up paint present, front windshield stone chip, interior dirt/stain, aero parts scuff/scratch.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 R5 / 3月	メーカー レクサス	ドア数 5	ボディ形状 SUV/クロカン	評価点 4.5
車種 乗用車・その他 ()	グレード L X	排気量 3440 cc	駆動方式 2WD	内装 A・⑤・C
車検 10年3月 / 抹消	燃料 ガソリン	型式 3BA-VJ A310W	ディーゼル	後付選用品 ()
走行 64,069 km	シフト オート	変速機 AT	ハイブリッド ()	後付選用品 ()
外装色 ソニックホワイト	カラーNo. 085	エアコン AG・⑤・WAG・ ()	新車登録 7人	新車登録 ()
左・ ()	ディーラー	販売	18,980円	PS・⑤・④・③・②・①
セールスポイント		修復歴 有・⑥		
検査記入欄		A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損		
シートスレ トリムA 内装うす汚れ 外装うすA ドア開閉 タッチパネル		名義中 月 日 まで VJ A310-4022623		
内装 シロ サブレ コグ コグ オーディオ		車検 0 km		