

2023 MAZDA Carol 5D GL Safe Support		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 3BA-HB37S	DISPLACEMENT 658 cc		
YEAR / REG. 2023/10	MILEAGE 14,901 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Other		
BODY TYPE Other			
CHASSIS NO. HB37S-103484	DIMENSIONS (L X W X H) 339 × 147 × 152 cm		
SALES POINTS			
Pre-Collision Braking			
INSPECTOR REPORT			
Minor scratches and dents. Interior trim has minor scratches. Carpet has scuffs. Door mirror has scratches, cracks, and breaks.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		型式番号	20232	納税証明書番号	0001	シリアル番号		評価点	
年	月	車名	グレード	駆動	4.5				
R 05	10	キャロル	5D	4WD					
型式	3BA-HB37S	排気量	660 cc	燃料	ガソリン	軽油		作業	A C
車検	年	月	車種	自家用	シフト	CVT	冷却	AC	純正装備品 ○をつける
走行距離	1	4	9	0	1	km	マイル	5 (交換)	純正ナビ
外観色	7-パ'ン'ガンバ-ルメタリック	色替	色替無	カラーNo.		内装色		純正ナビ	純正TV
車台No.	HB37S-103484	名義	期限	月	日	ナビ種類	(社外品含む) ○をつける	純正ナビ	純正TV
登録No.	豊橋	581	せ	7808	リサイクル	7,210円	未納税	純正ナビ	純正TV
定員	4 (人)	機軸重	kg	339	cm	147	cm	純正ナビ	純正TV
輸入車のみ	モデル	年式	輸入区分	ディーラー	登録	ハンドル	左	右	純正ナビ
セールスポイント 衝突被害軽減ブレーキ/後退時ブレーキサポート/ハイビームアシスト/電動格納式ドアミラー/シートヒーター/走行15,000km									
注意事項・不具合箇所 ★展示車の為、早い者勝ち！									
検査員記入欄・修理歴「有」の場合は修理箇所・交換箇所を記入 小A、U 内張り小A カベ'ットスレ									
ドアミラー キズ ヒビ ウレ 工費 ⑤ シャッキ ⑤									