

2023 MAZDA CX-60 2.5 25S L Package		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-KH5P	DISPLACEMENT 2,488 cc		
YEAR / REG. 2023/07	MILEAGE 15,285 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. KH5P-104158	DIMENSIONS (L X W X H) 474 × 189 × 169 cm		
SALES POINTS			
Alloy Wheels Leather Seats (Leather) Mazda Harmonic Acoustics (8 speakers)		Power Tailgate Adaptive Cruise Control	
INSPECTOR REPORT			
Front windshield: Scratches, stone chips, cracks, repair marks, replacement/major repair needed. Interior: Scratches, dirt, burns, holes, scuffs, tears, rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 令和5年7月	車名・グレード CX-60 25S Lパッケージ	2WD 4WD	評価点 (4.5)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 5BA-KH5P	排気量 2500 CC	ドア 5 形状 積載 kg
車歴 自家用	シフト FAT	定員 5人	外装 B
車検 令和8年7月(日)	冷房 AC	燃料 ガソリン	内装 B
走行 1万5千285 km	色 ブラック	色コード マイ	セールスポイント (正常に機能するものに限ります) キーレススマートキー★ETC★LEDヘッドライト パワーバックドア シースルービューパッケージ★M-DRIVE 12.3ディスプレイレザーシート 装備品 (純正品に限り○をつけてください) (PS) (PW) (AB) (AB) AW SR ナビ TV カワ
R券 15,890 円	注意事項申告欄	新車保証書 有・無	後日品 有・無
フロントガラス 内装	キズ・飛石・ヒビ割・リペア跡・X要 キズ・汚レ・コゲ・穴・スレ・キレ・破レ	スタッドレスタイヤ	スペア
車台番号 104158	登録番号 名変中	A-キズ E-エクゴ U-汚み W-補修跡 S-サビ C-腐食 XX-交換済	