

2023 MAZDA CX-60 3.3 XD L Package Diesel Turbo		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 3DA-KH3P	DISPLACEMENT 3,283 cc		
YEAR / REG. 2023/03	MILEAGE 56,005 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR White	BODY TYPE SUV		
CHASSIS NO. KH3P-106009	DIMENSIONS (L X W X H) 474 × 189 × 169 cm		
SALES POINTS			
Alloy Wheels Power Tailgate 360° Camera Mazda Harmonic Acoustics (8 speakers)		Leather Seats Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Trunk has scratches. Front glass has scratches, stone chips, cracks, repair marks, and requires replacement. Interior has scratches, dirt, burns, holes, scuffs, cuts, and tears.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 令和5 3月	車名・グレード CX-60 XD Lパッケージ	2WD 4WD	評価点 (4.5)
ディーラー・並行 モデル年式 年 ハンドル 左・右	型式 3DA-KH3P	排気量 3300 CC	ドア 5 形状 積載 5人 kg
車庫 自家用	シフト FAT	セールスポイント (正常に機能するものに限りです)	
車検 年 月 (日)	冷房 AAC	ギアレススマートキー・ETC・バックモニター	
走行 5万6千005 km	燃料 軽油	装備品 (純正品に限り○をつけてください)	
色 ホワイト	色コード 51K	(PS) SR	(PW) +ヒ
R券 15,890 円		(ABS) TV	(エアB) +フ
注意事項申告欄		新車保証書 有・無	後日品
前車 傷			
フロントガラス	キズ・飛石・ヒビ割・リペア跡・X要		
内装	(キズ)汚レ・コゲ・穴・スレ・キレ・破レ		
車台番号 106009		A-キズ E-エケボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済	
登録番号		型式指定番号 車検区別番号	