

|                                                                                                                                   |                                              |                                     |               |
|-----------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|-------------------------------------|---------------|
| 2023 MAZDA CX-8 2.2 XD Smart Edition<br>7-Seater                                                                                  |                                              | OVERALL<br>4.5                      |               |
|                                                                                                                                   |                                              | EXTERIOR<br>-                       | INTERIOR<br>- |
| MODEL CODE<br>3DA-KG2P                                                                                                            | DISPLACEMENT<br>2,188 cc                     |                                     |               |
| YEAR / REG.<br>2023/01                                                                                                            | MILEAGE<br>12,135 km                         |                                     |               |
| DOORS<br>5                                                                                                                        | SEATS<br>7                                   |                                     |               |
| TRANSMISSION<br>AT                                                                                                                | FUEL<br>Diesel                               |                                     |               |
| STEERING<br>Right                                                                                                                 | EXTERIOR COLOR<br>Other                      |                                     |               |
| BODY TYPE<br>Other                                                                                                                |                                              |                                     |               |
| CHASSIS NO.<br>KG2P-451139                                                                                                        | DIMENSIONS (L X W X H)<br>492 × 184 × 173 cm |                                     |               |
| SALES POINTS                                                                                                                      |                                              |                                     |               |
| Alloy Wheels<br>360° Camera                                                                                                       |                                              | Cruise Control<br>Navigation System |               |
| INSPECTOR REPORT                                                                                                                  |                                              |                                     |               |
| Light scratches on exterior, minor scuffs on seats, interior dirt and animal hair, steering wheel scuffs, headliner modification. |                                              |                                     |               |

ORIGINAL JAPANESE AUCTION SHEET

|                                               |             |         |       |          |                 |          |        |      |    |
|-----------------------------------------------|-------------|---------|-------|----------|-----------------|----------|--------|------|----|
| 出品票                                           |             | 型式番号    | 18723 | 車両種別     | 0427            | シリアル番号   |        | 評価点  |    |
| 年                                             | 月           | 日       | 車名    | グレード     | 駆動              | 4.5      |        |      |    |
| R 05                                          |             |         | CX-8  | 5        | 2.2 XDスタートED 7人 |          |        |      |    |
| 1                                             | 月           |         | 型式    | 3DA-KG2P | 排気量             | 2,200 cc | 燃料     | ガソリン | AT |
| 車種                                            | R 10        | 年       | 1     | 月        | 車歴              | 自家用      | シフト    | AT   | 冷蔵 |
| 走行距離                                          | 1           | 2       | 1     | 3        | 5               | km       | 0      | 1    | 2  |
| 外装色                                           | 元色          | シエッタラウマ | 色替    | 無        | カラーNo.          |          | 内装     |      |    |
| 車台No.                                         | KG2P-451139 |         |       | 車検       | 有効              | 期限       | 月      | 日    |    |
| 登録No.                                         | 川崎          | 336     | む     | 1204     | リサイクル           | 14,660円  | 未納税    |      |    |
| 定員                                            | 7人          | 乗客      | 乗客    | 乗客       | 492 cm          | 184 cm   | 173 cm |      |    |
| 輸入車のみ                                         | モデリ         | 車式      | 輸入区分  | ディーラー    | 並行              | ハンドル     | 左      |      |    |
| セールスポイント                                      |             |         |       |          |                 |          |        |      |    |
| 登録車 純正マツダコネク10.5インチナビ フルセグTV アラウンドビューカメラ アドバン |             |         |       |          |                 |          |        |      |    |
| スドスマートシティ                                     |             |         |       |          |                 |          |        |      |    |

|                               |    |      |    |
|-------------------------------|----|------|----|
| 注意事項・不具合箇所                    |    |      |    |
| 検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入 |    |      |    |
| 外装うすい傷                        |    |      |    |
| シートスレ小                        |    |      |    |
| 室内汚れ、動物の毛                     |    |      |    |
| ハンドルのすれ                       |    |      |    |
| 天候加工                          |    |      |    |
| ドアミラー                         | キズ | ヒビ   | フレ |
| 工務                            | ◎  | シヤッホ | 無  |

